| Recall Detail | |
|--|---|
| Ref No | 10000401 |
| Manufacturer | BMW |
| Vehicle Class | Passenger Car |
| Model/Type | M5 and M6 (F10, F12 and F13) |
| Dealer (phone no) | 31882677 |
| Subject | Replace the engine oil pump |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: (Last Seven Numbers) |
| Description of Defect, how it came to light, and possible consequences if ignored. | A manufacturing defect in the engine oil pump which may cause the engine pump fails and the engine could experience a sudden loss of oil pressure. Severe engine damage may result. |
| Remedial Action | Replace the engine oil pump |
| Build Dates | 07/2012 – 09/2012 |
| Launch Date | 26/09/2012 |
| Tentative Date of Recall Completion | 31/03/2013 |

| 1 | C967484 |
|----|---------|
| 2 | C967974 |
| 3 | C967975 |
| 4 | C968050 |
| 5 | C968064 |
| 6 | C968065 |
| 7 | DX95920 |
| 8 | DX95941 |
| 9 | DX95943 |
| 10 | DX95950 |
| 11 | DX95960 |
| 12 | DX95966 |
| 13 | DX95970 |
| 14 | DX95979 |
| 15 | DX95999 |
| 16 | DX96005 |
| | |