

Recall Detail

| | |
|---|---|
| Ref No | 10000506 |
| Manufacturer | Toyota |
| Vehicle Class | Private Car |
| Model/Type | Echo |
| Dealer (phone no) | Crown Motors Limited (Tel: 2880 4988) |
| Subject | Replacement of Driver's side Frontal Air Bag Inflator |
| Progress | Completed |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | The recall is related to the driver's side frontal air bag inflators which could have been assembled with improperly manufactured propellant wafers. Improperly manufactured propellant wafers could cause the inflator to rupture. In the case of a collision, the driver's side frontal air bag will be deployed abnormally which could result in increase of the risk of injury to the occupant. |
| Remedial Action | Replace the driver's air bag inflator |
| Build Dates | September 2002 ~ November 2003 |
| Launch Date | 27 November 2014 |
| Tentative Date of Recall Completion | July 2017 (completed) |