

Recall Detail

Ref No	10000586
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	smart fortwo/ 453
Dealer (phone no)	Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Yuen Long Service Centre: 2473 3171
Subject	Replace lock of maintenance flap (8892233)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	The locking forces of the maintenance flap may not correspond to the design specifications. At high vehicle speed in combination with strong gusts of wind, the maintenance flap may detach from the vehicle. The detachment of the maintenance flap from the vehicle increases the accident hazard and may pose an increased risk of injury for following road users.
Remedial Action	Replace the locks of the maintenance flap on affected vehicles as a precautionary measure
Build Dates	02/07/2015 - 05/08/2015
Launch Date	29/04/2016
Tentative Date of Recall Completion	31/12/2017

1	WME4533422K034889
2	WME4533422K034895
3	WME4533422K034911

4	WME4533422K034918
5	WME4533422K051601