

Recall Detail

Ref No	10000617
Manufacturer	Daimler AG
Vehicle Class	Heavy Goods Vehicle
Model/Type	Actros, Antos, Arocs / 936, 964
Dealer (phone no)	Zung Fu Commercial Vehicle Service Centre: 2637 2988
Subject	Pressure sensor of brake system leaky (4290283)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centre at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>Quality checks has shown that faulty axis modulators on the front and rear axle, proportional relay valves and the trailer control valve from WABCO may have been installed on your vehicle.</p> <p>It is possible that the applied brake pressure may be too great and can therefore deviate from the operation accustomed to by the driver. This could lead to an increased risk of accident.</p>
Remedial Action	As a precaution, replace the potentially affected brake components of the faulty batch.
Build Dates	14/07/2016 - 29/07/2016
Launch Date	21/9/2016
Tentative Date of Recall Completion	31/12/2017