

Recall Detail

Ref No	10000702
Manufacturer	Daimler AG
Vehicle Class	Bus
Model/Type	OC500RF Euro VI / 634407
Dealer (phone no)	Zung Fu Commercial Vehicle Service Centre: 2637 2988
Subject	Steering column bracket insufficiently welded (4692165)
Progress	Completed
Affected Vehicle Identification Number (VIN)	Please see below table.
Description of Defect, how it came to light, and possible consequences if ignored.	The weld seam on the steering column bracket is not sufficient on the affected vehicles.
Remedial Action	To subsequently weld the steering column bracket of affected vehicles as remedy.
Build Dates	20/07/2016 - 03/11/2016
Launch Date	14/06/2017
Tentative Date of Recall Completion	31/12/2017