| Recall Detail | |
|--|---|
| Ref No | 10000706 |
| Manufacturer | Daimler AG |
| Vehicle Class | Private car |
| Model/Type | E-Class / 213 |
| Dealer (phone no) | Zung Fu Aberdeen Service Centre:2552 8298Zung Fu Quarry Bay Service Centre:2563 4333Zung Fu Hunghom Service Centre:2363 9396Zung Fu Kwai Chung Service Centre:2427 3355Zung Fu Yuen Long Service Centre:2473 3171 |
| Subject | Replace oil feed line of exhaust gas turbochargers (0993037) |
| Progress | Completed |
| Affected Vehicle Identification Number (VIN) | Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. 2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fells into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall. |
| Description of Defect, how it came to light, and possible consequences if ignored. | The oil feed line for the exhaust gas turbochargers may not be leaktight. This could result in oil leaking from the oil feed line. It cannot be ruled out that this oil may come into contact with hot component parts while the vehicle is in operation. This would increase the risk of fire. |
| Remedial Action | Replace the oil feed line of the exhaust gas turbochargers on affected vehicles as a precautionary measure |
| Build Dates | 16/02/2017 - 02/05/2017 |
| Launch Date | 29/06/2017 |
| Tentative Date of Recall Completion | 31/12/2017 |