

Recall Detail

| | |
|-------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Ref No | 10000945 |
| Manufacturer | Daimler AG |
| Vehicle Class | Private car |
| Model/Type | GLE 450 4MATIC / 167 |
| Dealer (phone no) | Chai Wan Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140 |
| Subject | Welding of rear crossmember (6490004) |
| Progress | Completed |
| Affected Vehicle Identification Number (VIN) | <p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p> |
| Description of Defect, how it came to light, and possible consequences if ignored. | <p>The tensile strength of the welds on the rear crossmember of affected vehicles might not meet the specification.</p> <p>When the rear towing eye is used for towing, cracks might occur in the weld seams and the rear crossmember may detach from the vehicle, increasing the risk of a crash and/or injury for other road users.</p> |
| Remedial Action | Exchange the rear crossmember on affected vehicles as a precautionary measure. |
| Build Dates | 02/11/2019 |
| Launch Date | 10/06/2020 |
| Tentative Date of Recall Completion | 31/12/2020 |

1

WDC1671592A118974

2

WDC1671592A119084

3

WDC1671592A119159

4

WDC1671592A119337

| | |
|----|-------------------|
| 5 | WDC1671592A119556 |
| 6 | WDC1671592A119578 |
| 7 | WDC1671592A119588 |
| 8 | WDC1671592A119596 |
| 9 | WDC1671592A119988 |
| 10 | WDC1671592A120284 |
| 11 | WDC1671592A120583 |
| 12 | WDC1671592A120936 |