

## Recall Detail

<b>Ref No</b>	<b>10001007</b>
<b>Manufacturer</b>	Mercedes-Benz AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	GLB / 247
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
<b>Subject</b>	Wheel arch liner (8890088)
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>The wheel arch liners at the front fenders may not have been attached in affected vehicles in accordance with the specifications.</p> <p>As a result, it cannot be excluded that a wheel arch liner detaches from the vehicle during vehicle operation.</p> <p>This would increase the risk of an accident and/or injury for other road users.</p>
<b>Remedial Action</b>	Check the attachment of the front wheel arch liners in affected vehicles as a precautionary measure, and correctly install these if necessary.
<b>Build Dates</b>	10/02/2020 - 30/07/2020
<b>Launch Date</b>	16/04/2021
<b>Tentative Date of Recall Completion</b>	31/12/2021

1	W1N2476472W029683
2	W1N2476872W028783
3	W1N2476472W035049
4	W1N2476472W038651
5	W1N2476472W039196
6	W1N2476472W045285
7	W1N2476472W057289