

Recall Detail

Ref No	10001041
Manufacturer	Mercedes-Benz AG
Vehicle Class	Private car
Model/Type	E 200, GLC 300 4MATIC/ 213, 253
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
Subject	Airbag catch tab pressure sensor (9193112)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	In this case, it cannot be fully excluded that the connector of a side crash sensor may detach over the vehicle service life. This would result in the restraint systems being activated in a delayed manner in the event of a side crash, the restraint effect would possibly be reduced as a result.
Remedial Action	The side crash sensors in the doors will be checked, and replaced if necessary, as a precautionary measure in the affected vehicles.
Build Dates	04/08/2020 – 07/08/2020
Launch Date	09/08/2021
Tentative Date of Recall Completion	31/12/2022

1	W1K2130802A875402
2	W1K2130802A875416
3	W1K2130802A875441
4	W1K2130802A875453

5	W1K2130802A875467
6	W1K2130802A875481
7	W1K2130802A875497
8	W1K2130802A875529

9	W1K2130802A875538
10	W1K2130802A875547
11	W1N2533842F855980
12	W1N2533842F856284
13	W1N2533842F857118
14	W1N2533842F857366
15	W1N2533842F857485
16	W1N2539842F855902
17	W1N2539842F855957
18	W1N2539842F856097
19	W1N2539842F856883
20	W1N2539842F857557
21	W1N2539842F857953
22	W1K2130802A875402