

### 安全召回詳情

編號	<b>10000456</b>
製造商	BMW
車輛類別	私家車
型號	X1, X3, 3 系 and 5 系 (E8x, F1x, F2x and F3x)
代理商 (查詢電話)	31936688
主題	鑑別及檢查進氣凸輪軸
進度	進行中
受影響車輛的底盤號碼	見以下表列: (最後七位號碼)
缺陷簡述及忽略的可能後果	制動力輔助系統的效能可能無法得到保證。如此情況出現，司機需要施加更大的壓力在制動踏板上，把車輛減速。
修正行動	檢查及重新安裝進氣凸輪軸。如有需要，車輛的進氣凸輪軸會被更換。
製造日期	03/2011-10/2013
回收行動開始日期	14/12/2013
估計回收行動的完成日期	30/06/2014

1	<b>A269126</b>
2	<b>A269131</b>
3	<b>D291622</b>
4	<b>D291638</b>
5	<b>DX50345</b>
6	<b>DX50349</b>
7	<b>DX50350</b>
8	<b>DX50353</b>
9	<b>DX50357</b>
10	<b>DX50359</b>
11	<b>DX50360</b>
12	<b>DX50361</b>
13	<b>DX50362</b>
14	<b>DX50363</b>
15	<b>DX50364</b>
16	<b>DX50365</b>
17	<b>DX50367</b>
18	<b>DX50369</b>
19	<b>DX50374</b>
20	<b>DX50379</b>
21	<b>DX50380</b>
22	<b>DX50382</b>
23	<b>DX50386</b>

24	<b>DX50387</b>
25	<b>DX50389</b>
26	<b>DX50408</b>
27	<b>DX50418</b>
28	<b>DX50438</b>
29	<b>DX50441</b>
30	<b>DX50442</b>
31	<b>DX50450</b>
32	<b>DX50453</b>
33	<b>DX50456</b>
34	<b>DX50465</b>
35	<b>DX50466</b>
36	<b>DX50470</b>
37	<b>DX50471</b>
38	<b>DX50473</b>
39	<b>DX50474</b>
40	<b>DX50483</b>
41	<b>DX50488</b>
42	<b>DX50507</b>
43	<b>DX50508</b>
44	<b>DX50511</b>
45	<b>DX50516</b>
46	<b>DX50518</b>