

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
1		JMYSREA2AVZ000584
2		JMYSREA2AVZ000880
3		JMYSREA2AWZ001740
4		JMYSREA2AXZ003786
5		JMYSREA4AVZ000478
6		JMYSREA4AVZ000544
7		JMYSREA4AVZ001110
8		JMYSREA4AWZ000341
9		JMYSREA4AXZ000365
10		JMYSREA4AVZ000481
11		EA4A0000128
12		JMYSREA2AVZ001652
13		JMYSREA2AVZ003368
14		JMYSREA2AXZ003795
15		JMYSREA2AVZ001209
16		JMYSREA2AXZ002053
17		JMYSREA4AWZ000110
18		JMYSREA4AXZ000121
19		JMYSREA4AWZ000104
20	HE1820	EA4A0000112
21	LA1489	EA4A0000188
22	LE1250	EA4A0000189
23	GK1882	EC5A0002909
24	HB1350	JMYSREA2AVZ000634
25	HJ1393	JMYSREA2AVZ000699
26	KX1877	JMYSREA2AVZ000744
27	HP1723	JMYSREA2AVZ003117
28	FA1171	JMYSREA2AWZ004297
29	BC1251	JMYSREA2AXZ002671
30	LT1833	JMYSREA4AVZ000112

	Reg Mark	Chassis Number
31	KT1864	JMYSREA4AVZ000191
32	HH1166	JMYSREA4AVZ000208
33	LD1507	JMYSREA4AVZ000223
34	JT1936	JMYSREA4AVZ000277
35	LT1760	JMYSREA4AVZ000391
36	HD1981	JMYSREA4AVZ000517
37	FF1979	JMYSREA4AVZ000540
38	KW1083	JMYSREA4AVZ000562
39	GG1983	JMYSREA4AVZ000588
40	EZ1488	JMYSREA4AVZ000641
41	JM149	JMYSREA4AVZ000658
42	DW150	JMYSREA4AVZ000674
43	KM173	JMYSREA4AVZ000695
44	EB1611	JMYSREA4AVZ000722
45	CZ1488	JMYSREA4AVZ000727
46	FR1909	JMYSREA4AVZ000903
47	HF193	JMYSREA4AVZ000906
48	KR1680	JMYSREA4AVZ000977
49	LU1171	JMYSREA4AVZ001049
50	FM1892	JMYSREA4AVZ001086
51	CH1848	JMYSREA4AVZ001155
52	LL1120	JMYSREA4AVZ001232
53	HJ1029	JMYSREA4AVZ001427
54		JMYSREA4AVZ001429
55	FL1981	JMYSREA4AVZ001522
56	JU1242	JMYSREA4AVZ001539
57	KV1722	JMYSREA4AVZ001711
58	FK1996	JMYSREA4AVZ001730
59	HR1439	JMYSREA4AVZ001738
60	KA1884	JMYSREA4AWZ000116

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
61	JN1860	JMYSREA4AWZ000193
62	JT1739	JMYSREA4AXZ000454
63	JT1678	JMYSREA7A1Z000119
64	JU1788	JMYSREA7A1Z000121
65	JY1652	JMYSYEA3A1Z000101
66	FE156	JMYSREA4AVZ000254
67	EB1877	JMYSREA4AVZ000259
68	DK1193	JMYSREA4AVZ001163
69	GG185	JMYSREA4AVZ001339
70	LD1541	JMYSREA2AVZ003046
71	FJ1285	JMYSREA4AWZ000224
72	GM1290	JMYSREA2AVZ000637
73	HH1667	JMYSREA2AVZ002691
74	HG1629	JMYSREA2AVZ002920
75	JK1963	JMYSREA2AXZ003860
76	JE1722	JMYSREA4AVZ000947
77	HH1116	JMYSREA4AVZ001224
78	LN1244	JMYSREA4AVZ001448
79	HU1706	JMYSREA4AWZ000154
80	KY1266	JMYSREA4AWZ000232
81	LN1594	JMYSREA4AWZ000318
82	HN248	EA4A0000167
83	HB2583	JMYSREA2AVZ000800
84	KS2948	JMYSREA2AVZ001275
85	HD2795	JMYSREA2AVZ001341
86	EB271	JMYSREA2AVZ002650
87	HL2820	JMYSREA2AVZ003319
88	HP2835	JMYSREA2AWZ001639
89	LD2904	JMYSREA4AVZ000168
90	LP2149	JMYSREA4AVZ000171

	Reg Mark	Chassis Number
91	JK2175	JMYSREA4AVZ000244
92	HD2329	JMYSREA4AVZ000297
93	JB2296	JMYSREA4AVZ000317
94	HJ217	JMYSREA4AVZ000336
95	LJ2318	JMYSREA4AVZ000360
96	LE2023	JMYSREA4AVZ000483
97	LR2996	JMYSREA4AVZ000560
98	HS2711	JMYSREA4AVZ000653
99	HE293	JMYSREA4AVZ000850
100	HX2700	JMYSREA4AVZ000890
101	BE2282	JMYSREA4AVZ000968
102	BH2666	JMYSREA4AVZ000987
103	FB2098	JMYSREA4AVZ001242
104	HH2901	JMYSREA4AVZ001316
105	HP270	JMYSREA4AVZ001370
106	LL204	JMYSREA4AVZ001456
107	HL2837	JMYSREA4AVZ001492
108	JZ2119	JMYSREA4AVZ001590
109	HM2859	JMYSREA4AVZ001614
110	HY266	JMYSREA4AVZ001622
111	LR2493	JMYSREA4AVZ001648
112	LP2675	JMYSREA4AVZ001670
113	DH281	JMYSREA4AVZ001729
114	KF2889	JMYSREA4AWZ000166
115	KE208	JMYSREA4AWZ000362
116	HR2988	JMYSREA4AWZ000606
117	JF2892	JMYSREA4AXZ000289
118	JK2364	JMYSREA4AXZ000355
119	HE2817	JMYSREA4AVZ000760
120	HF2248	JMYSREA4AVZ000959

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
121	HG2281	JMYSREA4AVZ001171
122	FL2899	EA4A0000120
123	LH2216	EA4A0000199
124	HH2695	JMYSREA2AVZ002759
125	HH2398	JMYSREA2AVZ003042
126	HL2698	JMYSREA2AVZ003104
127	HP2915	JMYSREA2AVZ003690
128	HD2068	JMYSREA4AVZ000523
129	HF231	JMYSREA4AVZ001082
130	FP2682	JMYSREA4AVZ001279
131	FR2666	JMYSREA4AVZ001525
132	KM2909	JMYSREA4AVZ001534
133	HL2656	JMYSREA4AVZ001576
134	JB2421	JMYSREA4AXZ000111
135	HD3337	EA4A0000179
136	LH3714	EA4A0000205
137	CF3611	EC5A0100893
138	HM337	EC5A0300624
139	KH3551	JMYSREA2AVZ000631
140	CH317	JMYSREA2AVZ003089
141	LB3273	JMYSREA2AWZ001689
142	HU3963	JMYSREA2AWZ003609
143	JR3100	JMYSREA2AXZ003853
144	HB3342	JMYSREA4AVZ000146
145	FX3877	JMYSREA4AVZ000201
146	HD3111	JMYSREA4AVZ000372
147	JH3775	JMYSREA4AVZ000432
148	KH3596	JMYSREA4AVZ000458
149	HD3603	JMYSREA4AVZ000521
150	CL3221	JMYSREA4AVZ000768

	Reg Mark	Chassis Number
151	JW3614	JMYSREA4AVZ000821
152	CV3989	JMYSREA4AVZ000897
153	JV3201	JMYSREA4AVZ000949
154	HF3530	JMYSREA4AVZ001009
155	HF3310	JMYSREA4AVZ001032
156	ER3386	JMYSREA4AVZ001048
157	JR3328	JMYSREA4AVZ001105
158	DT348	JMYSREA4AVZ001130
159	HL3474	JMYSREA4AVZ001141
160	LB3768	JMYSREA4AVZ001158
161	LA3715	JMYSREA4AVZ001190
162	EW3285	JMYSREA4AVZ001234
163	HJ3689	JMYSREA4AVZ001244
164	KB3843	JMYSREA4AVZ001447
165	HL3616	JMYSREA4AVZ001511
166	KK3674	JMYSREA4AVZ001530
167	HL3758	JMYSREA4AVZ001549
168	HM3380	JMYSREA4AVZ001585
169	HR3380	JMYSREA4AVZ001587
170	HM3673	JMYSREA4AVZ001610
171	LT3217	JMYSREA4AVZ001664
172	DY3892	JMYSREA4AVZ001739
173	DR360	JMYSREA4AWZ000117
174	HP3385	JMYSREA4AWZ000129
175	LA3114	JMYSREA4AWZ000174
176	HV3648	JMYSREA4AWZ000316
177	GG3765	JMYSREA4AWZ000395
178	JW3396	JMYSREA4AWZ000421
179	EB3356	JMYSREA4AWZ000440
180	LE3326	JMYSREA4AWZ000460

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
181	JA3588	JMYSREA4AXZ000103
182	FM316	JMYSREA4AXZ000443
183	HE3299	EA4A0000123
184	KE3821	JMYSREA4AVZ000128
185	HA3382	JMYSREA4AVZ000261
186	HD3646	JMYSREA4AVZ000383
187	HB337	JMYSREA4AVZ000495
188	CD3389	JMYSREA4AVZ000534
189	HD3343	JMYSREA4AVZ000576
190	FY3217	JMYSREA4AVZ000585
191	CS347	JMYSREA4AVZ000724
192	HF3476	JMYSREA4AVZ001075
193	ED3163	JMYSREA4AVZ001112
194	JA399	JMYSREA4AXZ000117
195	HC3087	JMYSREA2AVZ000821
196	HB3996	JMYSREA4AVZ000151
197	KB3188	JMYSREA4AVZ000210
198	HD3632	JMYSREA4AVZ000610
199	HE3403	JMYSREA4AVZ000849
200	ER3973	JMYSREA4AVZ001026
201	KX3320	JMYSREA4AVZ001340
202	HH3187	JMYSREA4AVZ001366
203	HL3940	JMYSREA4AVZ001523
204	LF3596	JMYSREA4AVZ001745
205	HZ3310	JMYSREA4AXZ000102
206	LG3921	JMYSREA4AXZ000241
207	EE3007	JMYSREA4AXZ000389
208	EY4151	EA4A0000133
209	JM4878	EC5A0100619
210	HA4978	JMYSREA2AVZ000619

	Reg Mark	Chassis Number
211	JZ4107	JMYSREA2AVZ000784
212	HG4962	JMYSREA2AVZ002446
213	HY4083	JMYSREA2AWZ004468
214	HY4014	JMYSREA2AWZ004628
215	LH4533	JMYSREA2AXZ002453
216	KT4760	JMYSREA2AXZ002491
217	JG4110	JMYSREA2AXZ002692
218	JE4482	JMYSREA4AVZ000229
219	LB403	JMYSREA4AVZ000245
220	JN4398	JMYSREA4AVZ000371
221	GD440	JMYSREA4AVZ000637
222	HV450	JMYSREA4AVZ000639
223	HE403	JMYSREA4AVZ000734
224	LR4501	JMYSREA4AVZ000997
225	FH4486	JMYSREA4AVZ001324
226	LN4093	JMYSREA4AVZ001344
227	FJ498	JMYSREA4AVZ001642
228	HM4632	JMYSREA4AVZ001728
229	KC4401	JMYSREA4AWZ000238
230	LP4954	JMYSREA4AWZ000335
231	GA4810	JMYSREA4AWZ000376
232	HY4801	JMYSREA4AWZ000417
233	LA4913	JMYSREA4AXZ000107
234	KJ4303	JMYSREA4AXZ000231
235	KM422	JMYSREA4AXZ000464
236	HD4350	JMYSREA4AVZ000449
237	HD4415	JMYSREA4AVZ000579
238	HF4097	JMYSREA4AVZ001000
239	HJ4373	JMYSREA4AVZ001415
240	HM4295	JMYSREA4AVZ001639

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
241	KD4544	EA4A0000208
242	HX4223	EC5A0100628
243	HM4504	JMYSREA2AVZ003109
244	LD4325	JMYSREA4AVZ000570
245	KX4865	JMYSREA4AVZ001081
246	LG4162	JMYSREA4AVZ001093
247	JR4420	JMYSREA4AVZ001469
248	FX408	JMYSREA4AWZ000103
249	HP4357	JMYSREA4AWZ000168
250	HV4229	JMYSREA4AWZ000425
251	GK4327	JMYSREA4AXZ000128
252	HR5852	EA4A0000132
253	JG5568	EC5A0100585
254	HF512	JMYSREA2AVZ001353
255	HR5280	JMYSREA2AWZ001679
256	HA5902	JMYSREA2AWZ002950
257	KF517	JMYSREA2AWZ004651
258	FG529	JMYSREA2AXZ001587
259	JM5099	JMYSREA2AXZ003951
260	JR5116	JMYSREA2AXZ004099
261	JV5813	JMYSREA4AVZ000156
262	JD5703	JMYSREA4AVZ000251
263	LL5326	JMYSREA4AVZ000262
264	HC5026	JMYSREA4AVZ000283
265	KY5498	JMYSREA4AVZ000331
266	KL5917	JMYSREA4AVZ000402
267	HD5730	JMYSREA4AVZ000426
268	LP5255	JMYSREA4AVZ000484
269	LT5969	JMYSREA4AVZ000486
270	JT5472	JMYSREA4AVZ000584

	Reg Mark	Chassis Number
271	LB542	JMYSREA4AVZ000589
272	HE5677	JMYSREA4AVZ000601
273	HJ5702	JMYSREA4AVZ000633
274	KD5092	JMYSREA4AVZ000719
275	KJ5138	JMYSREA4AVZ000769
276	LK5315	JMYSREA4AVZ000820
277	JX5106	JMYSREA4AVZ000860
278	HZ5540	JMYSREA4AVZ000877
279	AS512	JMYSREA4AVZ000941
280	LN5752	JMYSREA4AVZ001061
281	JZ5312	JMYSREA4AVZ001170
282	HL5890	JMYSREA4AVZ001220
283	HG5991	JMYSREA4AVZ001243
284	GZ5612	JMYSREA4AVZ001372
285	HJ5255	JMYSREA4AVZ001439
286	JW5368	JMYSREA4AVZ001577
287	KJ5437	JMYSREA4AVZ001625
288	HM5796	JMYSREA4AVZ001663
289	HN5288	JMYSREA4AWZ000114
290	HP5520	JMYSREA4AWZ000122
291	LR508	JMYSREA4AWZ000144
292	JC5941	JMYSREA4AWZ000146
293	KV5003	JMYSREA4AWZ000148
294	JA5700	JMYSREA4AWZ000456
295	JD5220	JMYSREA4AXZ000163
296	HD5179	JMYSREA4AVZ000436
297	HD574	JMYSREA4AVZ000547
298	EV5188	JMYSREA4AVZ000581
299	HH5476	EC5A0002908
300	HA5761	EA4A0000141

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
301	LG5789	EC5A0300665
302	HA5145	JMYSREA2AVZ000641
303	HJ5679	JMYSREA2AVZ003095
304	HR5395	JMYSREA2AVZ003120
305	HC5090	JMYSREA4AVZ000281
306	KN5214	JMYSREA4AVZ000296
307	CC523	JMYSREA4AVZ000438
308	FN5970	JMYSREA4AVZ000705
309	HF5644	JMYSREA4AVZ001046
310	HJ5271	JMYSREA4AVZ001116
311	LR5063	JMYSREA4AVZ001458
312	KM5478	JMYSREA4AVZ001631
313	KM5261	JMYSREA4AVZ001649
314	JS5715	JMYSREA4AVZ001747
315	KY6850	EA4A0000111
316	JC6766	EA4A0000121
317	KW6630	JMYSREA2AVZ000934
318	DD602	JMYSREA2AVZ001143
319	296	JMYSREA2AVZ001309
320	LM6438	JMYSREA2AVZ001315
321	HH6647	JMYSREA2AVZ002898
322	JY6578	JMYSREA2AXZ001639
323	JM6272	JMYSREA2AXZ003938
324	KF6308	JMYSREA4AVZ000123
325	KM6370	JMYSREA4AVZ000141
326	JZ6923	JMYSREA4AVZ000149
327	JL6045	JMYSREA4AVZ000155
328	JL6673	JMYSREA4AVZ000192
329	LJ6436	JMYSREA4AVZ000219
330	FU6876	JMYSREA4AVZ000238

	Reg Mark	Chassis Number
331	KE6663	JMYSREA4AVZ000248
332	JT6366	JMYSREA4AVZ000310
333	FV605	JMYSREA4AVZ000340
334	KF6330	JMYSREA4AVZ000407
335	HD648	JMYSREA4AVZ000416
336	FA6169	JMYSREA4AVZ000477
337	KE6189	JMYSREA4AVZ000485
338	KH6032	JMYSREA4AVZ000532
339	HD6293	JMYSREA4AVZ000599
340	JM6248	JMYSREA4AVZ000600
341	LT6808	JMYSREA4AVZ000696
342	JU6874	JMYSREA4AVZ000712
343	HD6962	JMYSREA4AVZ000747
344	JM6960	JMYSREA4AVZ000884
345	LS693	JMYSREA4AVZ000957
346	HE6823	JMYSREA4AVZ000978
347	KF632	JMYSREA4AVZ001102
348	JY6437	JMYSREA4AVZ001208
349	LF6904	JMYSREA4AVZ001367
350	FH6899	JMYSREA4AVZ001418
351	HJ6488	JMYSREA4AVZ001444
352	KJ615	JMYSREA4AVZ001633
353	KW6834	JMYSREA4AWZ000126
354	FS6872	JMYSREA4AWZ000210
355	CH663	JMYSREA4AWZ000481
356	JA6143	JMYSREA4AXZ000142
357	JW6715	JMYSREA4AXZ000159
358	JF6938	JMYSREA4AXZ000206
359	GB6663	JMYSREA4AXZ000211
360	ES661	JMYSREA4AXZ000458

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
361	GW683	JMYSREA4AVZ000291
362	JY6080	JMYSREA4AVZ000667
363	DU6881	JMYSREA4AVZ001104
364	HH6697	JMYSREA4AVZ001211
365	HH6049	JMYSREA4AVZ001257
366	HM6830	JMYSREA4AVZ001589
367	EF6879	JMYSREA4AVZ001742
368	JF6698	JMYSREA4AXZ000444
369	HC6263	JMYSREA2AVZ000803
370	JV6697	JMYSREA2AVZ001330
371	DY6238	JMYSREA2AVZ002853
372	BW6898	JMYSREA2AVZ003092
373	DH6860	JMYSREA4AVZ000140
374	DJ6833	JMYSREA4AVZ000247
375	JP609	JMYSREA4AVZ000349
376	KW6626	JMYSREA4AVZ000503
377	KN6375	JMYSREA4AVZ000609
378	HB6003	JMYSREA4AVZ000654
379	HD6631	JMYSREA4AVZ000805
380	JA6732	JMYSREA4AVZ000806
381	JH6392	JMYSREA4AVZ000902
382	JS6897	JMYSREA4AVZ000909
383	HX6797	JMYSREA4AWZ000369
384	HW7072	EA4A0000165
385	HA7456	EA4A0000171
386	KM7947	EC5A0002904
387	HL7720	JMYSREA2AVZ003103
388	LL7083	JMYSREA2AVZ003306
389	FD7188	JMYSREA2AWZ001537
390	HT7085	JMYSREA2AWZ001697

	Reg Mark	Chassis Number
391	HT7329	JMYSREA2AWZ002848
392	JD7148	JMYSREA2AXZ002437
393	GK7822	JMYSREA2AXZ003850
394	7273	JMYSREA4AVZ000181
395	KG7145	JMYSREA4AVZ000209
396	HC7757	JMYSREA4AVZ000423
397	HC7673	JMYSREA4AVZ000435
398	KC7871	JMYSREA4AVZ000490
399	KF7283	JMYSREA4AVZ000513
400	HD7131	JMYSREA4AVZ000565
401	LR7257	JMYSREA4AVZ000688
402	LV7100	JMYSREA4AVZ000771
403	CV734	JMYSREA4AVZ000773
404	CU729	JMYSREA4AVZ000793
405	LH7904	JMYSREA4AVZ000800
406	KR7746	JMYSREA4AVZ000814
407	HB7739	JMYSREA4AVZ001126
408	KX7845	JMYSREA4AVZ001139
409	KZ7760	JMYSREA4AVZ001218
410	LR7608	JMYSREA4AVZ001219
411	KE7339	JMYSREA4AVZ001230
412	JT7522	JMYSREA4AVZ001299
413	LG7161	JMYSREA4AVZ001646
414	HM7003	JMYSREA4AVZ001661
415	HM7429	JMYSREA4AVZ001723
416	LK7384	JMYSREA4AWZ000208
417	HT721	JMYSREA4AWZ000252
418	DZ782	JMYSREA4AWZ000351
419	HT7906	JMYSREA4AWZ000400
420	KT768	JMYSREA4AWZ000471

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
421	JU730	JMYSREA4AXZ000126
422	FZ7773	JMYSREA4AXZ000359
423	HD7042	JMYSREA4AXZ000360
424	JS7736	JMYSREA4AXZ000445
425	LF7188	JMYSREA7A1Z000111
426	JU7397	JMYSREA7A1Z000142
427	JL7156	EC5A0002910
428	HC7096	JMYSREA4AVZ000377
429	HD7469	JMYSREA4AVZ000618
430	HF7430	JMYSREA4AVZ001095
431	HH7859	JMYSREA4AVZ001225
432	HH7719	JMYSREA4AVZ001271
433	HP7315	JMYSREA4AWZ000186
434	KB7012	EA4A0000151
435	KW7863	JMYSREA2AXZ001649
436	LR7307	JMYSREA4AVZ000207
437	KT7860	JMYSREA4AVZ000224
438	JU7415	JMYSREA4AVZ000625
439	HD7142	JMYSREA4AVZ000661
440	KW7756	JMYSREA4AVZ000692
441	BM7783	JMYSREA4AVZ000807
442	KV7457	JMYSREA4AVZ000840
443	HF7955	JMYSREA4AVZ001039
444	JN7282	JMYSREA4AVZ001428
445	HR7119	JMYSREA4AWZ000138
446	HS7467	JMYSREA4AWZ000286
447	JF7189	JMYSREA4AXZ000240
448	JU730	JMYSREA7A1Z000126
449	HT8033	EA4A0000144
450	CN8687	EA4A0000172

	Reg Mark	Chassis Number
451	LD8308	EA4A0000200
452	CX829	EA4A0000207
453	HH8726	JMYSREA2AVZ000879
454	HB8878	JMYSREA2AVZ000950
455	KU8497	JMYSREA2AVZ001208
456	EU897	JMYSREA2AVZ001382
457	FY8381	JMYSREA2AVZ003118
458	DR8889	JMYSREA2AWZ003134
459	JA8938	JMYSREA4AVZ000108
460	KP8582	JMYSREA4AVZ000152
461	LA8408	JMYSREA4AVZ000183
462	HR850	JMYSREA4AVZ000205
463	HC8445	JMYSREA4AVZ000266
464	HC8457	JMYSREA4AVZ000301
465	KB8102	JMYSREA4AVZ000326
466	LR8083	JMYSREA4AVZ000358
467	HS8242	JMYSREA4AVZ000405
468	HA884	JMYSREA4AVZ000556
469	MH8857	JMYSREA4AVZ000559
470	HD8481	JMYSREA4AVZ000594
471	EE8609	JMYSREA4AVZ000615
472	LD8344	JMYSREA4AVZ000672
473	HD8923	JMYSREA4AVZ000707
474	HD8793	JMYSREA4AVZ000749
475	HD8081	JMYSREA4AVZ000751
476	AY8766	JMYSREA4AVZ000755
477	HE8892	JMYSREA4AVZ000803
478	LN8980	JMYSREA4AVZ000832
479	HD834	JMYSREA4AVZ000846
480	LR8316	JMYSREA4AVZ000861

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
481	JJ8658	JMYSREA4AVZ000867
482	KU8346	JMYSREA4AVZ000894
483	KJ8450	JMYSREA4AVZ000969
484	GW8588	JMYSREA4AVZ001023
485	LA8737	JMYSREA4AVZ001117
486	AA880	JMYSREA4AVZ001119
487	JY840	JMYSREA4AVZ001165
488	LK8554	JMYSREA4AVZ001181
489	HG8921	JMYSREA4AVZ001206
490	HG8417	JMYSREA4AVZ001252
491	HH8742	JMYSREA4AVZ001320
492	HG8655	JMYSREA4AVZ001350
493	HJ8198	JMYSREA4AVZ001441
494	EY884	JMYSREA4AVZ001503
495	KZ8033	JMYSREA4AWZ000180
496	FA8216	JMYSREA4AWZ000201
497	LH8895	JMYSREA4AWZ000266
498	KX8434	JMYSREA4AWZ000278
499	KB8221	JMYSREA4AWZ000300
500	KX8858	JMYSREA4AWZ000308
501	HV8949	JMYSREA4AWZ000385
502	HX836	JMYSREA4AWZ000446
503	LE835	JMYSREA4AWZ000468
504	JA864	JMYSREA4AXZ000122
505	JA8412	JMYSREA4AXZ000165
506	JF8553	JMYSREA4AXZ000236
507	JC809	JMYSREA4AXZ000467
508	HC8494	JMYSREA4AVZ000385
509	he8081	JMYSREA4AVZ000693
510	HE8795	JMYSREA4AVZ000889

	Reg Mark	Chassis Number
511	GS834	JMYSREA4AVZ000982
512	HJ8662	JMYSREA4AVZ001388
513	HJ8204	JMYSREA4AVZ001484
514	DY8388	JMYSREA4AWZ000124
515	EU8422	EA4A0000149
516	HE8012	JMYSREA2AVZ001172
517	JF8090	JMYSREA2AXZ002058
518	HF8522	JMYSREA2AXZ002467
519	JW8862	JMYSREA4AVZ000659
520	HD8169	JMYSREA4AVZ000770
521	DK8682	JMYSREA4AVZ000962
522	LT8648	JMYSREA4AVZ001013
523	KX8909	JMYSREA4AVZ001025
524	BX8892	JMYSREA4AVZ001056
525	LA8846	JMYSREA4AVZ001058
526	HF8910	JMYSREA4AVZ001077
527	EZ8832	JMYSREA4AVZ001136
528	FS805	JMYSREA4AVZ001572
529	DM8810	JMYSREA4AWZ000150
530	EA8666	JMYSREA4AWZ000329
531	HR8813	JMYSREA4AWZ000344
532	EM8018	JMYSREA4AWZ000452
533	HU8315	JMYSREA4AWZ000479
534	JD8941	JMYSREA4AXZ000133
535	JJ8918	JMYSREA4AXZ000366
536	LF9746	EA4A0000118
537	HB995	JMYSREA2AVZ000626
538	FW9700	JMYSREA2AVZ000633
539	HE9770	JMYSREA2AVZ000638
540	KG9690	JMYSREA2AVZ000787

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
541	HG9001	JMYSREA2AVZ003054
542	JH916	JMYSREA2AVZ003066
543	HJ9549	JMYSREA2AVZ003072
544	HV9253	JMYSREA2AWZ003238
545	KT9443	JMYSREA4AVZ000133
546	HB9926	JMYSREA4AVZ000169
547	LJ9451	JMYSREA4AVZ000190
548	HB9883	JMYSREA4AVZ000230
549	FH9938	JMYSREA4AVZ000348
550	DG9092	JMYSREA4AVZ000381
551	HD9190	JMYSREA4AVZ000462
552	EL9278	JMYSREA4AVZ000473
553]W9084	JMYSREA4AVZ000624
554	HE9533	JMYSREA4AVZ000694
555	LG9672	JMYSREA4AVZ000746
556	AG906	JMYSREA4AVZ000750
557	LE9118	JMYSREA4AVZ000816
558	JC9935	JMYSREA4AVZ000852
559	JH9045	JMYSREA4AVZ000868
560	LA9247	JMYSREA4AVZ000876
561	HE9939	JMYSREA4AVZ000888
562	EG923	JMYSREA4AVZ000945
563	HE9143	JMYSREA4AVZ000946
564	HE9921	JMYSREA4AVZ000976
565	FF9030	JMYSREA4AVZ001070
566	GE9763	JMYSREA4AVZ001114
567	HF9012	JMYSREA4AVZ001133
568	HG9346	JMYSREA4AVZ001290
569	HG9666	JMYSREA4AVZ001295
570	HG9060	JMYSREA4AVZ001336

	Reg Mark	Chassis Number
571	HG9388	JMYSREA4AVZ001347
572	DM9693	JMYSREA4AVZ001414
573	LM9279	JMYSREA4AVZ001632
574	LA9330	JMYSREA4AVZ001732
575	LR9323	JMYSREA4AWZ000453
576	GM9209	JMYSREA4AWZ000462
577	JA9485	JMYSREA4AXZ000140
578	HG977	JMYSREA4AXZ000144
579	CU9996	JMYSREA4AVZ000129
580	EY9188	JMYSREA4AVZ000606
581	HD9208	JMYSREA4AVZ000786
582	EX9986	JMYSREA4AWZ000231
583	GV9175	JMYSREA2AVZ002522
584	HB9461	JMYSREA4AVZ000197
585	JV9020	JMYSREA4AVZ000457
586	EK991	JMYSREA4AVZ000915
587	KZ9188	JMYSREA4AVZ000936
588	KL9377	JMYSREA4AVZ001038
589	JV9144	JMYSREA4AVZ001091
590	HF9964	JMYSREA4AVZ001122
591	ES932	JMYSREA4AVZ001338
592	DV9313	JMYSREA4AVZ001406
593	JE9252	JMYSREA4AVZ001516
594	KH9949	JMYSREA4AVZ001708
595	LL9831	JMYSREA4AWZ000212
596	GB9298	JMYSREA4AXZ000476
597	JT9203	JMYSREA7A1Z000127
598	GF287	JMYSREA4AVZ001454
599	HG1213	JMYSREA4AWZ000261
600	JW3889	JMYSREA4AXZ000416

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A, EC5A

項目 Subject: 檢查下搖臂接頭

Inspection of lateral lower arm ball joint, Replacement if out of specification

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
601	JL2220	JMYSREA4AVZ001501
602	CM3233	JMYSREA4AVZ000595
603	HP3929	JMYSREA4AVZ000537