

安全召回詳情

編號	10000115
製造商	Land Rover
車輛類別	
型號	Discovery Series II
代理商 (查詢電話)	Land Rover Hong Kong (Tel:2713 1068)
主題	Active Cornering Enhancement-Torque Concern
進度	已完成
受影響車輛的底盤號碼	N/A
缺陷簡述及忽略的可能後果	The banjo connection which secures the Active Cornering Enhancement(ACE) high pressure pipe to the pump may loosen and under certain conditions may allow a fluid leak, which would revert the vehicle handling back to non-ACE operation. In extreme case, should the vehicle continue to be driven, the fluid leak could lead to fire. The loss of fluid would be progressively accompanied by amber and red warning lights on the instrument console.
修正行動	Re-torque and replace banjo bolt washers
製造日期	13.12.1999 to 30.9.2003
回收行動開始日期	31/03/2004
回收行動的完成日期	17/07/2012