

安全召回詳情

編號	10000116
製造商	Land Rover
車輛類別	
型號	Discovery Series II
代理商 (查詢電話)	Land Rover Hong Kong (Tel:2713 1068)
主題	Incorrect Throttle Operation
進度	已完成
受影響車輛的底盤號碼	N/A
缺陷簡述及忽略的可能後果	Misalignment of the spindle bush bore to the break-through bore on the potentiometer side of the throttle body can lead to incorrect throttle operation. Under certain circumstances cause the throttle spindle within the assembly to stick when the throttle pedal is released. Should this occur, the throttle may stick in an open position.
修正行動	Inspect the date code replace throttle body if necessary.
製造日期	27/01/2003 to 26/03/2003
回收行動開始日期	31/03/2004
回收行動的完成日期	17/07/2012