

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

1	JHMRA18500C000021	31	JHMRA18500C000051
2	JHMRA18500C000022	32	JHMRA18500C000052
3	JHMRA18500C000023	33	JHMRA18500C000053
4	JHMRA18500C000024	34	JHMRA18500C000054
5	JHMRA18500C000025	35	JHMRA18500C000055
6	JHMRA18500C000026	36	JHMRA18500C000056
7	JHMRA18500C000027	37	JHMRA18500C000057
8	JHMRA18500C000028	38	JHMRA18500C000058
9	JHMRA18500C000029	39	JHMRA18500C000059
10	JHMRA18500C000030	40	JHMRA18500C000060
11	JHMRA18500C000031	41	JHMRA18500C000061
12	JHMRA18500C000032	42	JHMRA18500C000062
13	JHMRA18500C000033	43	JHMRA18500C000063
14	JHMRA18500C000034	44	JHMRA18500C000064
15	JHMRA18500C000035	45	JHMRA18500C000065
16	JHMRA18500C000036	46	JHMRA18500C000066
17	JHMRA18500C000037	47	JHMRA18500C000067
18	JHMRA18500C000038	48	JHMRA18500C000068
19	JHMRA18500C000039	49	JHMRA18500C000069
20	JHMRA18500C000040	50	JHMRA18500C000070
21	JHMRA18500C000041	51	JHMRA18500C000071
22	JHMRA18500C000042	52	JHMRA18500C000072
23	JHMRA18500C000043	53	JHMRA18500C000073
24	JHMRA18500C000044	54	JHMRA18500C000074
25	JHMRA18500C000045	55	JHMRA18500C000075
26	JHMRA18500C000046	56	JHMRA18500C000076
27	JHMRA18500C000047	57	JHMRA18500C000077
28	JHMRA18500C000048	58	JHMRA18500C000078
29	JHMRA18500C000049	59	JHMRA18500C000079
30	JHMRA18500C000050	60	JHMRA18500C000080

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda  
型號 Model: Odyssey  
項目 Subject: 更換點火器  
Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

61	JHMRA18500C000081	91	JHMRA18500C000111
62	JHMRA18500C000082	92	JHMRA18500C000112
63	JHMRA18500C000083	93	JHMRA18500C000113
64	JHMRA18500C000084	94	JHMRA18500C000114
65	JHMRA18500C000085	95	JHMRA18500C000115
66	JHMRA18500C000086	96	JHMRA18500C000116
67	JHMRA18500C000087	97	JHMRA18500C000117
68	JHMRA18500C000088	98	JHMRA18500C000118
69	JHMRA18500C000089	99	JHMRA18500C000119
70	JHMRA18500C000090	100	JHMRA18500C000120
71	JHMRA18500C000091	101	JHMRA18500C000121
72	JHMRA18500C000092	102	JHMRA18500C000122
73	JHMRA18500C000093	103	JHMRA18500C000123
74	JHMRA18500C000094	104	JHMRA18500C000124
75	JHMRA18500C000095	105	JHMRA18500C000125
76	JHMRA18500C000096	106	JHMRA18500C000126
77	JHMRA18500C000097	107	JHMRA18500C000127
78	JHMRA18500C000098	108	JHMRA18500C000128
79	JHMRA18500C000099	109	JHMRA18500C000129
80	JHMRA18500C000100	110	JHMRA18500C000130
81	JHMRA18500C000101	111	JHMRA18500C000131
82	JHMRA18500C000102	112	JHMRA18500C000132
83	JHMRA18500C000103	113	JHMRA18500C000133
84	JHMRA18500C000104	114	JHMRA18500C000134
85	JHMRA18500C000105	115	JHMRA18500C000135
86	JHMRA18500C000106	116	JHMRA18500C000136
87	JHMRA18500C000107	117	JHMRA18500C000137
88	JHMRA18500C000108	118	JHMRA18500C000138
89	JHMRA18500C000109	119	JHMRA18500C000139
90	JHMRA18500C000110	120	JHMRA18500C000140

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

121	JHMRA18500C000141	151	JHMRA18500C000191
122	JHMRA18500C000142	152	JHMRA18500C000192
123	JHMRA18500C000143	153	JHMRA18500C000193
124	JHMRA18500C000144	154	JHMRA18500C000194
125	JHMRA18500C000145	155	JHMRA18500C000195
126	JHMRA18500C000146	156	JHMRA18500C000196
127	JHMRA18500C000147	157	JHMRA18500C000197
128	JHMRA18500C000148	158	JHMRA18500C000198
129	JHMRA18500C000149	159	JHMRA18500C000199
130	JHMRA18500C000150	160	JHMRA18500C000200
131	JHMRA18500C000152	161	JHMRA18500C000201
132	JHMRA18500C000153	162	JHMRA18500C000202
133	JHMRA18500C000154	163	JHMRA18500C000203
134	JHMRA18500C000155	164	JHMRA18500C000204
135	JHMRA18500C000156	165	JHMRA18500C000205
136	JHMRA18500C000157	166	JHMRA18500C000206
137	JHMRA18500C000158	167	JHMRA18500C000207
138	JHMRA18500C000159	168	JHMRA18500C000208
139	JHMRA18500C000160	169	JHMRA18500C000209
140	JHMRA18500C000161	170	JHMRA18500C000210
141	JHMRA18500C000162	171	JHMRA18500C000211
142	JHMRA18500C000163	172	JHMRA18500C000212
143	JHMRA18500C000164	173	JHMRA18500C000213
144	JHMRA18500C000165	174	JHMRA18500C000214
145	JHMRA18500C000166	175	JHMRA18500C000215
146	JHMRA18500C000167	176	JHMRA18500C000216
147	JHMRA18500C000168	177	JHMRA18500C000217
148	JHMRA18500C000169	178	JHMRA18500C000218
149	JHMRA18500C000170	179	JHMRA18500C000219
150	JHMRA18500C000176	180	JHMRA18500C000220

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda  
型號 Model: Odyssey  
項目 Subject: 更換點火器  
Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

181	JHMRA18500C000221	211	JHMRA18500C000251
182	JHMRA18500C000222	212	JHMRA18500C000252
183	JHMRA18500C000223	213	JHMRA18500C000253
184	JHMRA18500C000224	214	JHMRA18500C000254
185	JHMRA18500C000225	215	JHMRA18500C000255
186	JHMRA18500C000226	216	JHMRA18500C000256
187	JHMRA18500C000227	217	JHMRA18500C000257
188	JHMRA18500C000228	218	JHMRA18500C000259
189	JHMRA18500C000229	219	JHMRA18500C000260
190	JHMRA18500C000230	220	JHMRA18500C000261
191	JHMRA18500C000231	221	JHMRA18500C000263
192	JHMRA18500C000232	222	JHMRA18500C000264
193	JHMRA18500C000233	223	JHMRA18500C000265
194	JHMRA18500C000234	224	JHMRA18500C000266
195	JHMRA18500C000235	225	JHMRA18500C000268
196	JHMRA18500C000236	226	JHMRA18500C000269
197	JHMRA18500C000237	227	JHMRA18500C000270
198	JHMRA18500C000238	228	JHMRA18500C000271
199	JHMRA18500C000239	229	JHMRA18500C000272
200	JHMRA18500C000240	230	JHMRA18500C000273
201	JHMRA18500C000241	231	JHMRA18500C000274
202	JHMRA18500C000242	232	JHMRA18500C000275
203	JHMRA18500C000243	233	JHMRA18500C000276
204	JHMRA18500C000244	234	JHMRA18500C000277
205	JHMRA18500C000245	235	JHMRA18500C000278
206	JHMRA18500C000246	236	JHMRA18500C000279
207	JHMRA18500C000247	237	JHMRA18500C000280
208	JHMRA18500C000248	238	JHMRA18500C000281
209	JHMRA18500C000249	239	JHMRA18500C000282
210	JHMRA18500C000250	240	JHMRA18500C000283

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

241	JHMRA18500C000284	271	JHMRA18500C000381
242	JHMRA18500C000285	272	JHMRA18500C000439
243	JHMRA18500C000286	273	JHMRA18500C000440
244	JHMRA18500C000287	274	JHMRA18500C000441
245	JHMRA18500C000288	275	JHMRA18500C000469
246	JHMRA18500C000289	276	JHMRA18500C000470
247	JHMRA18500C000290	277	JHMRA18500C000471
248	JHMRA18500C000291	278	JHMRA18500C000472
249	JHMRA18500C000292	279	JHMRA18500C000473
250	JHMRA18500C000293	280	JHMRA18500C000474
251	JHMRA18500C000294	281	JHMRA18500C000475
252	JHMRA18500C000295	282	JHMRA18500C000493
253	JHMRA18500C000296	283	JHMRA18500C000494
254	JHMRA18500C000297	284	JHMRA18500C000495
255	JHMRA18500C000299	285	JHMRA18500C000496
256	JHMRA18500C000300	286	JHMRA18500C000497
257	JHMRA18500C000301	287	JHMRA18500C000498
258	JHMRA18500C000302	288	JHMRA18500C000507
259	JHMRA18500C000303	289	JHMRA18500C000508
260	JHMRA18500C000304	290	JHMRA18500C000509
261	JHMRA18500C000305	291	JHMRA18500C000510
262	JHMRA18500C000306	292	JHMRA18500C000511
263	JHMRA18500C000307	293	JHMRA18500C000512
264	JHMRA18500C000308	294	JHMRA18500C000513
265	JHMRA18500C000309	295	JHMRA18500C000522
266	JHMRA18500C000310	296	JHMRA18500C000523
267	JHMRA18500C000312	297	JHMRA18500C000524
268	JHMRA18500C000314	298	JHMRA18500C000525
269	JHMRA18500C000315	299	JHMRA18500C000526
270	JHMRA18500C000316	300	JHMRA18500C000527

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

301	JHMRA18500C000536
302	JHMRA18500C000538
303	JHMRA18500C000539
304	JHMRA18500C000540
305	JHMRA18500C000541
306	JHMRA18500C000542
307	JHMRA18500C000543
308	JHMRA18500C000553
309	JHMRA18500C000554
310	JHMRA18500C000555
311	JHMRA18500C000556
312	JHMRA18500C000557
313	JHMRA18500C000558
314	JHMRA18500C000559
315	JHMRA18500C000568
316	JHMRA18500C000569
317	JHMRA18500C000570
318	JHMRA18500C000571
319	JHMRA18500C000572
320	JHMRA18500C000573
321	JHMRA18500C000574
322	JHMRA18500C000575
323	JHMRA18500C000584
324	JHMRA18500C000585
325	JHMRA18500C000586
326	JHMRA18500C000587
327	JHMRA18500C000588
328	JHMRA18500C000589
329	JHMRA18500C000590
330	JHMRA18500C000599

331	JHMRA18500C000600
332	JHMRA18500C000601
333	JHMRA18500C000602
334	JHMRA18500C000603
335	JHMRA18500C000604
336	JHMRA18500C000605
337	JHMRA18500C000614
338	JHMRA18500C000615
339	JHMRA18500C000616
340	JHMRA18500C000617
341	JHMRA18500C000618
342	JHMRA18500C000619
343	JHMRA18500C000620
344	JHMRA18500C000621
345	JHMRA18500C000630
346	JHMRA18500C000631
347	JHMRA18500C000632
348	JHMRA18500C000633
349	JHMRA18500C000634
350	JHMRA18500C000635
351	JHMRA18500C000636
352	JHMRA18500C000649
353	JHMRA18500C000650
354	JHMRA18500C000651
355	JHMRA18500C000652
356	JHMRA18500C000653
357	JHMRA18500C000654
358	JHMRA18500C000655
359	JHMRA18500C000656
360	JHMRA18500C000668

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

361	JHMRA18500C000669	391	JHMRA18500C003100
362	JHMRA18500C000670	392	JHMRA18500C003101
363	JHMRA18500C000671	393	JHMRA18500C003140
364	JHMRA18500C000672	394	JHMRA18500C003141
365	JHMRA18500C000673	395	JHMRA18500C003142
366	JHMRA18500C000674	396	JHMRA18500C003143
367	JHMRA18500C000675	397	JHMRA18500C003144
368	JHMRA18500C000676	398	JHMRA18500C003184
369	JHMRA18500C000677	399	JHMRA18500C003185
370	JHMRA18500C000678	400	JHMRA18500C003186
371	JHMRA18500C002952	401	JHMRA18500C003187
372	JHMRA18500C002953	402	JHMRA18500C003188
373	JHMRA18500C002955	403	JHMRA18500C003236
374	JHMRA18500C002956	404	JHMRA18500C003237
375	JHMRA18500C002957	405	JHMRA18500C003238
376	JHMRA18500C003002	406	JHMRA18500C003239
377	JHMRA18500C003003	407	JHMRA18500C003240
378	JHMRA18500C003004	408	JHMRA18500C003241
379	JHMRA18500C003005	409	JHMRA18500C003287
380	JHMRA18500C003006	410	JHMRA18500C003288
381	JHMRA18500C003007	411	JHMRA18500C003289
382	JHMRA18500C003052	412	JHMRA18500C003290
383	JHMRA18500C003053	413	JHMRA18500C003291
384	JHMRA18500C003054	414	JHMRA18500C003336
385	JHMRA18500C003055	415	JHMRA18500C003337
386	JHMRA18500C003056	416	JHMRA18500C003338
387	JHMRA18500C003096	417	JHMRA18500C003339
388	JHMRA18500C003097	418	JHMRA18500C003340
389	JHMRA18500C003098	419	JHMRA18500C003341
390	JHMRA18500C003099	420	JHMRA18500C003387

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

421	JHMRA18500C003388	451	JHMRA18500C003642
422	JHMRA18500C003389	452	JHMRA18500C003707
423	JHMRA18500C003390	453	JHMRA18500C003708
424	JHMRA18500C003391	454	JHMRA18500C003709
425	JHMRA18500C003436	455	JHMRA18500C003710
426	JHMRA18500C003437	456	JHMRA18500C003711
427	JHMRA18500C003438	457	JHMRA18500C003748
428	JHMRA18500C003439	458	JHMRA18500C003749
429	JHMRA18500C003440	459	JHMRA18500C003750
430	JHMRA18500C003441	460	JHMRA18500C003751
431	JHMRA18500C003490	461	JHMRA18500C003752
432	JHMRA18500C003491	462	JHMRA18500C003791
433	JHMRA18500C003492	463	JHMRA18500C003792
434	JHMRA18500C003493	464	JHMRA18500C003793
435	JHMRA18500C003494	465	JHMRA18500C003794
436	JHMRA18500C003539	466	JHMRA18500C003795
437	JHMRA18500C003540	467	JHMRA18500C003836
438	JHMRA18500C003541	468	JHMRA18500C003837
439	JHMRA18500C003542	469	JHMRA18500C003838
440	JHMRA18500C003543	470	JHMRA18500C003839
441	JHMRA18500C003588	471	JHMRA18500C003876
442	JHMRA18500C003589	472	JHMRA18500C003877
443	JHMRA18500C003590	473	JHMRA18500C003917
444	JHMRA18500C003591	474	JHMRA18500C003957
445	JHMRA18500C003592	475	JHMRA18500C003958
446	JHMRA18500C003637	476	JHMRA18500C003959
447	JHMRA18500C003638	477	JHMRA18500C004053
448	JHMRA18500C003639	478	JHMRA18500C004054
449	JHMRA18500C003640	479	JHMRA18500C004147
450	JHMRA18500C003641	480	JHMRA18500C004148



# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda  
型號 Model: Odyssey  
項目 Subject: 更換點火器  
Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

481	JHMRA18500C004149	511	JHMRA18500C005779
482	JHMRA18500C004245	512	JHMRA18500C005780
483	JHMRA18500C004444	513	JHMRA18500C005849
484	JHMRA18500C004585	514	JHMRA18500C005850
485	JHMRA18500C004586	515	JHMRA18500C005919
486	JHMRA18500C004587	516	JHMRA18500C005920
487	JHMRA18500C004621	517	JHMRA18500C005970
488	JHMRA18500C004624	518	JHMRA18500C005971
489	JHMRA18500C004627	519	JHMRA18500C005972
490	JHMRA18500C004628	520	JHMRA18500C005973
491	JHMRA18500C004715	521	JHMRA18500C005974
492	JHMRA18500C004716	522	JHMRA18500C005975
493	JHMRA18500C004717	523	JHMRA18500C005976
494	JHMRA18500C004765	524	JHMRA18500C005977
495	JHMRA18500C004766	525	JHMRA18500C005978
496	JHMRA18500C004767	526	JHMRA18500C005979
497	JHMRA18500C004815	527	JHMRA18500C005980
498	JHMRA18500C004816	528	JHMRA18500C005981
499	JHMRA18500C004817	529	JHMRA18500C005982
500	JHMRA18500C004865	530	JHMRA18500C005983
501	JHMRA18500C004866	531	JHMRA18500C005984
502	JHMRA18500C004867	532	JHMRA18500C005985
503	JHMRA18500C004915	533	JHMRA18500C005986
504	JHMRA18500C004963	534	JHMRA18500C005987
505	JHMRA18500C005010	535	JHMRA18500C005988
506	JHMRA18500C005011	536	JHMRA18500C005989
507	JHMRA18500C005054	537	JHMRA18500C005990
508	JHMRA18500C005055	538	JHMRA18500C006059
509	JHMRA18500C005100	539	JHMRA18500C006060
510	JHMRA18500C005146	540	JHMRA18500C006109

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

541	JHMRA18500C006126	571	JHMRA18800C100494
542	JHMRA18500C006127	572	JHMRA18800C100495
543	JHMRA18500C006128	573	JHMRA18800C100538
544	JHMRA18500C006129	574	JHMRA18800C100539
545	JHMRA18500C006169	575	JHMRA18800C100618
546	JHMRA18500C006189	576	JHMRA18800C100696
547	JHMRA18500C006209	577	JHMRA18800C100697
548	JHMRA18500C006229	578	JHMRA18800C100698
549	JHMRA18500C006247	579	JHMRA18800C100699
550	JHMRA18500C006248	580	JHMRA18800C100700
551	JHMRA18500C006249	581	JHMRA18800C100701
552	JHMRA18500C006326	582	JHMRA18800C100702
553	JHMRA18500C006327	583	JHMRA18800C100703
554	JHMRA18500C006328	584	JHMRA18800C100704
555	JHMRA18500C006329	585	JHMRA18800C100739
556	JHMRA18500C006367	586	JHMRA18800C100740
557	JHMRA18500C006368	587	JHMRA18800C100741
558	JHMRA18500C006403	588	JHMRA18800C100742
559	JHMRA18500C006421	589	JHMRA18800C100743
560	JHMRA18500C006456	590	JHMRA18800C100744
561	JHMRA18800C100122	591	JHMRA18800C100745
562	JHMRA18800C100123	592	JHMRA18800C100746
563	JHMRA18800C100166	593	JHMRA18800C100902
564	JHMRA18800C100167	594	JHMRA18800C100903
565	JHMRA18800C100213	595	JHMRA18800C100904
566	JHMRA18800C100258	596	JHMRA18800C100905
567	JHMRA18800C100303	597	JHMRA18800C100906
568	JHMRA18800C100348	598	JHMRA18800C100907
569	JHMRA18800C100393	599	JHMRA18800C100908
570	JHMRA18800C100450	600	JHMRA18800C100909

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

601	JHMRA18800C100950	631	JHMRA18800C101290
602	JHMRA18800C100951	632	JHMRA18800C101291
603	JHMRA18800C100952	633	JHMRA18800C101292
604	JHMRA18800C100953	634	JHMRA18800C101293
605	JHMRA18800C100954	635	JHMRA18800C101294
606	JHMRA18800C100955	636	JHMRA18800C101396
607	JHMRA18800C100956	637	JHMRA18800C101397
608	JHMRA18800C100957	638	JHMRA18800C101425
609	JHMRA18800C101081	639	JHMRA18800C101426
610	JHMRA18800C101082	640	JHMRA18800C101514
611	JHMRA18800C101083	641	JHMRA18800C101539
612	JHMRA18800C101124	642	JHMRA18800C101540
613	JHMRA18800C101125	643	JHMRA18800C101541
614	JHMRA18800C101126	644	JHMRA18800C101542
615	JHMRA18800C101127	645	JHMRA18800C101543
616	JHMRA18800C101128	646	JHMRA18800C101568
617	JHMRA18800C101129	647	JHMRA18800C101569
618	JHMRA18800C101130	648	JHMRA18800C101570
619	JHMRA18800C101131	649	JHMRA18800C101571
620	JHMRA18800C101166	650	JHMRA18800C101572
621	JHMRA18800C101167	651	JHMRA18800C102070
622	JHMRA18800C101168	652	JHMRA18800C102071
623	JHMRA18800C101169	653	JHMRA18800C102072
624	JHMRA18800C101170	654	JHMRA18800C102073
625	JHMRA18800C101171	655	JHMRA18800C102089
626	JHMRA18800C101172	656	JHMRA18800C102090
627	JHMRA18800C101173	657	JHMRA18800C102091
628	JHMRA18800C101287	658	JHMRA18800C102092
629	JHMRA18800C101288	659	JHMRA18800C102171
630	JHMRA18800C101289	660	JHMRA18800C102172

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

661	JHMRA18800C102173	691	JHMRA18800C102577
662	JHMRA18800C102174	692	JHMRA18800C102578
663	JHMRA18800C102190	693	JHMRA18800C102579
664	JHMRA18800C102191	694	JHMRA18800C102580
665	JHMRA18800C102192	695	JHMRA18800C102581
666	JHMRA18800C102193	696	JHMRA18800C102604
667	JHMRA18800C102210	697	JHMRA18800C102605
668	JHMRA18800C102211	698	JHMRA18800C102606
669	JHMRA18800C102212	699	JHMRA18800C102607
670	JHMRA18800C102213	700	JHMRA18800C102628
671	JHMRA18800C102380	701	JHMRA18800C102629
672	JHMRA18800C102381	702	JHMRA18800C102630
673	JHMRA18800C102382	703	JHMRA18800C102631
674	JHMRA18800C102406	704	JHMRA18800C102632
675	JHMRA18800C102407	705	JHMRA18800C102779
676	JHMRA18800C102430	706	JHMRA18800C102842
677	JHMRA18800C102431	707	JHMRA18800C102843
678	JHMRA18800C102432	708	JHMRA18800C102844
679	JHMRA18800C102456	709	JHMRA18800C102845
680	JHMRA18800C102457	710	JHMRA18800C102859
681	JHMRA18800C102479	711	JHMRA18800C102860
682	JHMRA18800C102480	712	JHMRA18800C102861
683	JHMRA18800C102481	713	JHMRA18800C102862
684	JHMRA18800C102482	714	JHMRA18800C102863
685	JHMRA18800C102529	715	JHMRA18800C102864
686	JHMRA18800C102530	716	JHMRA18800C102961
687	JHMRA18800C102531	717	JHMRA18800C102962
688	JHMRA18800C102532	718	JHMRA18800C102963
689	JHMRA18800C102556	719	JHMRA18800C102964
690	JHMRA18800C102557	720	JHMRA18800C102965

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

721	JHMRA18800C102966	751	JHMRA18800C103364
722	JHMRA18800C102967	752	JHMRA18800C103451
723	JHMRA18800C102981	753	JHMRA18800C103524
724	JHMRA18800C102982	754	JHMRA18800C103525
725	JHMRA18800C102983	755	JHMRA18800C103526
726	JHMRA18800C102984	756	JHMRA18800C103527
727	JHMRA18800C102985	757	JHMRA18800C103528
728	JHMRA18800C102986	758	JHMRA18800C103529
729	JHMRA18800C102987	759	JHMRA18800C103560
730	JHMRA18800C102988	760	JHMRA18800C103561
731	JHMRA18800C103168	761	JHMRA18800C103562
732	JHMRA18800C103169	762	JHMRA18800C103563
733	JHMRA18800C103170	763	JHMRA18800C103564
734	JHMRA18800C103171	764	JHMRA18800C103565
735	JHMRA18800C103172	765	JHMRA18800C103600
736	JHMRA18800C103173	766	JHMRA18800C103601
737	JHMRA18800C103174	767	JHMRA18800C103602
738	JHMRA18800C103243	768	JHMRA18800C103603
739	JHMRA18800C103244	769	JHMRA18800C103785
740	JHMRA18800C103245	770	JHMRA18800C103786
741	JHMRA18800C103246	771	JHMRA18800C103862
742	JHMRA18800C103247	772	JHMRA18800C103863
743	JHMRA18800C103248	773	JHMRA18800C103864
744	JHMRA18800C103249	774	JHMRA18800C103865
745	JHMRA18800C103250	775	JHMRA18800C104064
746	JHMRA18800C103251	776	JHMRA18800C104184
747	JHMRA18800C103328	777	JHMRA18800C104185
748	JHMRA18800C103360	778	JHMRA18800C104186
749	JHMRA18800C103362	779	JHMRA18800C104261
750	JHMRA18800C103363	780	JHMRA18800C104262

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda  
型號 Model: Odyssey  
項目 Subject: 更換點火器  
Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

781	JHMRA18800C104263	811	JHMRA18800C104987
782	JHMRA18800C104264	812	JHMRA18800C104988
783	JHMRA18800C104265	813	JHMRA18800C104989
784	JHMRA18800C104382	814	JHMRA18800C104990
785	JHMRA18800C104383	815	JHMRA18800C104991
786	JHMRA18800C104384	816	JHMRA18800C105100
787	JHMRA18800C104462	817	JHMRA18800C105101
788	JHMRA18800C104463	818	JHMRA18800C105213
789	JHMRA18800C104595	819	JHMRA18800C105309
790	JHMRA18800C104596	820	JHMRA18800C105310
791	JHMRA18800C104654	821	JHMRA18800C105311
792	JHMRA18800C104655	822	JHMRA18800C105312
793	JHMRA18800C104656	823	JHMRA18800C105358
794	JHMRA18800C104657	824	JHMRA18800C105359
795	JHMRA18800C104658	825	JHMRA18800C105360
796	JHMRA18800C104707	826	JHMRA18800C105361
797	JHMRA18800C104826	827	JHMRA18800C105403
798	JHMRA18800C104893	828	JHMRA18800C105404
799	JHMRA18800C104894	829	JHMRA18800C105405
800	JHMRA18800C104895	830	JHMRA18800C105406
801	JHMRA18800C104896	831	JHMRA18800C105407
802	JHMRA18800C104897	832	JHMRA18800C105408
803	JHMRA18800C104898	833	JHMRA18800C105409
804	JHMRA18800C104928	834	JHMRA18800C105410
805	JHMRA18800C104929	835	JHMRA18800C105449
806	JHMRA18800C104930	836	JHMRA18800C105450
807	JHMRA18800C104931	837	JHMRA18800C105451
808	JHMRA18800C104984	838	JHMRA18800C105452
809	JHMRA18800C104985	839	JHMRA18800C105453
810	JHMRA18800C104986	840	JHMRA18800C105454

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

### Involved Vehicle Identification Numbers

841	JHMRA18800C105455
842	JHMRA18800C105456
843	JHMRA18800C105457
844	JHMRA18800C105458
845	JHMRA18800C105459
846	JHMRA18800C105493
847	JHMRA18800C105494
848	JHMRA18800C105495
849	JHMRA18800C105496
850	JHMRA18800C105497
851	JHMRA18800C105498
852	JHMRA18800C105499
853	JHMRA18800C105500
854	JHMRA18800C105501
855	JHMRA18800C105546
856	JHMRA18800C105548
857	JHMRA18800C105550
858	JHMRA18800C105554
859	JHMRA18800C105555
860	JHMRA18800C105556
861	JHMRA18800C105557
862	JHMRA18800C105603
863	JHMRA18800C105604
864	JHMRA18800C105605
865	JHMRA18800C105606
866	JHMRA18800C105693
867	JHMRA18800C105702
868	JHMRA18800C105703
869	JHMRA18800C105704
870	JHMRA18800C105745

871	JHMRA18800C105746
872	JHMRA18800C105747
873	JHMRA18800C105748
874	JHMRA18800C105749
875	JHMRA18800C105750
876	JHMRA18800C105751
877	JHMRA18800C105803
878	JHMRA18800C105847
879	JHMRA18800C105848
880	JHMRA18800C105849
881	JHMRA18800C105850
882	JHMRA18800C105940
883	JHMRA18800C105941
884	JHMRA18800C105942
885	JHMRA18800C105943
886	JHMRA18800C105944
887	JHMRA18800C105945
888	JHMRA18800C105946
889	JHMRA18800C105947
890	JHMRA18800C105948