Recall Detail

Ref No	**10001163**
Manufacturer	Mitsubishi Fuso Truck & Bus Corporation
Vehicle Class	Medium Goods Vehicle / Heavy Goods Vehicle
Model/Type	Fuso FV70
Dealer (phone no)	Universal Cars Limited (Tel: 39138818)
Subject	PDM (Power Distribution Module) harness misrouting
Progress	**Running**
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The PDM (Power Distribution Module) wiring harness routing is incorrect. Depending on RHD / LHD configuration, the incorrect harness routing affects positive or positive / negative respectively. In a worst-case scenario, the wiring might get damaged due to interference with the PDM bracket, and short-circuit resulting in a vehicle fire.
Remedial Action	Check the wiring harness of the positive side power supply wiring to the PDM on all affected vehicles, and if the harness is incorrectly routed, reroute it to the correctly.
Build Dates	01/03/2022
Launch Date	04/03/2024
Tentative Date of Recall Completion	03/03/2027

1	FV70HKA20002
2	FV70HPA20002
3	FV70HSA20003