| Recall Detail | |
|---|---|
| **Ref No** | **10001247** |
| **Manufacturer** | BMW |
| **Vehicle Class** | Passenger Car |
| **Model/Type** | 318i, 323i, 328i (E46) with M43 TU, M52 TU engine |
| **Dealer (phone no)** | To Kwa Wan BMW-Customer Relation Department (31936688) |
| **Subject** | Replace the driver's airbag (0032970200) |
| **Progress** | **Running** |
| **Affected Vehicle Identification Number (VIN)** | List as below |
| **Description of Defect, how it came to light, and possible consequences if ignored.** | Driver's airbag – It's gas generator, in case if this is exposed to high absolute air humidity for a period of years and/or there are quality deficiencies in the production of the gas generator. When the driver's airbag is triggered in the regular fashion, this may result in high internal pressure in the gas generator. In unfavorable cases, the gas generator may split and metal parts may escape from the airbag. |
| **Remedial Action** | Replace the driver's airbag |
| **Build Dates** | 30/07/1998 – 09/11/1998 |
| **Launch Date** | 02/12/2019 |
| **Tentative Date of Recall Completion** | 31/12/2030 |

| | |
|---|---|
| 1 | WBAAL32000FH53941 |
| 2 | WBAAL32000FH54412 |
| 3 | WBAAL32000FH54524 |
| 4 | WBAAL32000FH54877 |
| 5 | WBAAL32000FH54880 |
| 6 | WBAAL32000FH54944 |
| 7 | WBAAL32000FH55298 |
| 8 | WBAAL32000FH55320 |
| 9 | WBAAL32000FH55477 |
| 10 | WBAAL32000FH55480 |
| 11 | WBAAL32000FH55494 |
| 12 | WBAAL32000FH55527 |
| 13 | WBAAL32000FH55561 |
| 14 | WBAAL32010FH54418 |
| 15 | WBAAL32010FH54547 |
| 16 | WBAAL32010FH55293 |
| 17 | WBAAL32010FH55472 |
| 18 | WBAAL32010FH56590 |
| 19 | WBAAL32010FH57898 |
| 20 | WBAAL32020FH53939 |
| 21 | WBAAL32020FH53942 |
| 22 | WBAAL32020FH54413 |
| 23 | WBAAL32020FH54430 |
| 24 | WBAAL32020FH54461 |
| 25 | WBAAL32020FH54900 |
| 26 | WBAAL32020FH55402 |
| 27 | WBAAL32020FH55447 |
| 28 | WBAAL32020FH55495 |
| 29 | WBAAL32020FH55500 |
| 30 | WBAAL32020FH56551 |
| 31 | WBAAL32030FH53819 |
| 32 | WBAAL32030FH54291 |
| 33 | WBAAL32030FH54419 |
| 34 | WBAAL32030FH54890 |
| 35 | WBAAL32030FH54906 |
| 36 | WBAAL32030FH55005 |
| 37 | WBAAL32030FH55019 |
| 38 | WBAAL32030FH55294 |
| 39 | WBAAL32030FH55408 |
| 40 | WBAAL32030FH55411 |
| 41 | WBAAL32030FH55442 |
| 42 | WBAAL32030FH55473 |
| 43 | WBAAL32030FH55523 |
| 44 | WBAAL32030FH55540 |
| 45 | WBAAL32040FH53473 |
| 46 | WBAAL32040FH53814 |

| | |
|---|---|
| 47 | WBAAL32040FH54431 |
| 48 | WBAAL32040FH55448 |
| 49 | WBAAL32040FH55482 |
| 50 | WBAAL32040FH55496 |
| 51 | WBAAL32040FH56521 |
| 52 | WBAAL32040FH58642 |
| 53 | WBAAL32050FH53966 |
| 54 | WBAAL32050FH54891 |
| 55 | WBAAL32050FH55300 |
| 56 | WBAAL32050FH55412 |
| 57 | WBAAL32050FH55443 |
| 58 | WBAAL32050FH55474 |
| 59 | WBAAL32060FH53958 |
| 60 | WBAAL32060FH53961 |
| 61 | WBAAL32060FH54415 |
| 62 | WBAAL32060FH54902 |
| 63 | WBAAL32060FH54978 |
| 64 | WBAAL32060FH55502 |
| 65 | WBAAL32060FH57914 |
| 66 | WBAAL32060FH58643 |
| 67 | WBAAL32070FH54519 |
| 68 | WBAAL32070FH54858 |
| 69 | WBAAL32070FH54889 |
| 70 | WBAAL32070FH54892 |

| | |
|---|---|
| 71 | WBAAL32070FH55279 |
| 72 | WBAAL32070FH55444 |
| 73 | WBAAL32070FH55475 |
| 74 | WBAAL32070FH55489 |
| 75 | WBAAL32070FH55539 |
| 76 | WBAAL32070FH56657 |
| 77 | WBAAL32080FH53959 |
| 78 | WBAAL32080FH53962 |
| 79 | WBAAL32080FH54464 |
| 80 | WBAAL32080FH54903 |
| 81 | WBAAL32080FH55002 |
| 82 | WBAAL32080FH55470 |
| 83 | WBAAL32080FH55503 |
| 84 | WBAAL32080FH56604 |
| 85 | WBAAL32080FH58577 |
| 86 | WBAAL32090FH53940 |
| 87 | WBAAL32090FH54411 |
| 88 | WBAAL32090FH55302 |
| 89 | WBAAL32090FH55400 |
| 90 | WBAAL32090FH55414 |
| 91 | WBAAL32090FH55445 |
| 92 | WBAAL32090FH55476 |
| 93 | WBAAL320X0FH53820 |
| 94 | WBAAL320X0FH53963 |

| | |
|---|---|
| 95 | WBAAL320X0FH54014 |
| 96 | WBAAL320X0FH54417 |
| 97 | WBAAL320X0FH54823 |
| 98 | WBAAL320X0FH55471 |
| 99 | WBAAL320X0FH58578 |
| 100 | WBAAL320X0FH58628 |
| 101 | WBAAM32000FP00098 |
| 102 | WBAAM32000FP00103 |
| 103 | WBAAM32010FP00059 |
| 104 | WBAAM32010FP00966 |
| 105 | WBAAM32020FP00099 |
| 106 | WBAAM32020FP00104 |
| 107 | WBAAM32030FP00063 |
| 108 | WBAAM32040FP00086 |
| 109 | WBAAM32040FP00105 |
| 110 | WBAAM32050FP00064 |
| 111 | WBAAM32050FP00095 |
| 112 | WBAAM32050FP00100 |
| 113 | WBAAM32060FP00090 |
| 114 | WBAAM32060FP00106 |
| 115 | WBAAM32070FP00096 |
| 116 | WBAAM32070FP00101 |
| 117 | WBAAM32080FP00057 |
| 118 | WBAAM32080FP00107 |

| | |
|---|---|
| 119 | WBAAM32090FP00102 |
| 120 | WBAAM320X0FP00089 |
| 121 | WBAAM51040EH68961 |
| 122 | WBAAM51060EH68976 |
| 123 | WBAAM51060FN70311 |
| 124 | WBAAM52040FK85346 |