Recall Detail	
Ref No	**10001252**
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	220i,318i,420i,430i,Z4 sDrive (G20,G22,G23,G29,G42) with B48C,B48D engine
Dealer (phone no)	To Kwa Wan BMW-Customer Relation Department (31936688)
Subject	Replace the starter motor (0012770600)
Progress	**Running**
Affected Vehicle Identification Number (VIN)	List as below
Description of Defect, how it came to light, and possible consequences if ignored.	As factory checks have shown that, frequent starting can lead to increased wear on the solenoid switch, which made the engine cannot starting again. Additionally, short circuits and localized overheating may occur. In this case, smoke or the smell of smoke may appear.
Remedial Action	Replace the starter motor
Build Dates	31/10/2022 – 03/04/2025
Launch Date	07/07/2026
Tentative Date of Recall Completion	31/12/2028

1	WBA12AP080CN24051
2	WBA12CM0308D58981
3	WBA20FF0108E91327
4	WBA20FF0208D36737
5	WBA20FF0308D33345
6	WBA20FF0308E31470
7	WBA20FF0308E94598
8	WBA20FF0408D42619
9	WBA20FF0508D33721
10	WBA20FF0508E34564
11	WBA20FF0608D26843
12	WBA20FF0608F55054
13	WBA20FF0708D27600
14	WBA20FF0708E67842
15	WBA20FF0808D27606
16	WBA20FF0808E91700
17	WBA20FF0908D26335
18	WBA20FF0908E51383
19	WBA20FF0908E93410
20	WBA20FF0X08D26263
21	WBA22AT010CM26084
22	WBA22AT020CM12646
23	WBA22AT080CM18404
24	WBA22AT090CM14975
25	WBA22AT0X0CM17058
26	WBAHF12060WY04883
27	WBAHF12080WY06229