Recall Detail	
Ref No	**10001253**
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	330e iPerformance (F30) with XB1H engine
Dealer (phone no)	To Kwa Wan BMW-Customer Relation Department (31936688)
Subject	Replace the starter motor (0012820600)
Progress	**Running**
Affected Vehicle Identification Number (VIN)	List as below
Description of Defect, how it came to light, and possible consequences if ignored.	As factory checks have shown that when moisture may have entered the starter motor causing oxidation, which made the engine cannot starting again. Additionally, short circuits and localized overheating may occur. In the event of an accident, there is a risk of fire.
Remedial Action	Replace the starter motor
Build Dates	18/11/2015 – 25/04/2018
Launch Date	08/07/2026
Tentative Date of Recall Completion	31/12/2028

1	WBA8E12000K794992
2	WBA8E12000K795835
3	WBA8E12010K795035
4	WBA8E12010K795617
5	WBA8E12010K795729
6	WBA8E12020K427429
7	WBA8E12020K795335
8	WBA8E12030A239203
9	WBA8E12030A239492
10	WBA8E12050A683764
11	WBA8E12050K795040
12	WBA8E12060A239695
13	WBA8E12060K795614
14	WBA8E12070K795038
15	WBA8E12070K795234
16	WBA8E12070K795444
17	WBA8E12080K795615
18	WBA8E12090A239366
19	WBA8E12090A683766
20	WBA8E12090K427430
21	WBA8E12090K795039
22	WBA8E12090K795834
23	WBA8E12090K795851
24	WBA8E120X0A239361