Recall Detail	
Ref No	**10001254**
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	530e iPerformance, 740e iPerformance, 740Le xDrive iPerformance (G11, G12, G30) with XB1H engine
Dealer (phone no)	To Kwa Wan BMW-Customer Relation Department (31936688)
Subject	Replace the starter motor (0012840600)
Progress	**Running**
Affected Vehicle Identification Number (VIN)	List as below
Description of Defect, how it came to light, and possible consequences if ignored.	As factory checks have shown that when moisture may have entered the starter motor causing oxidation, which made the engine cannot starting again. Additionally, short circuits and localized overheating may occur. In the event of an accident, there is a risk of fire.
Remedial Action	Replace the starter motor
Build Dates	15/07/2016 – 12/09/2018
Launch Date	08/07/2026
Tentative Date of Recall Completion	31/12/2028

1	WBA7D02040B314994
2	WBA7D02050B314812
3	WBA7D02080G510438
4	WBA7J22000G497107
5	WBA7J22010G497472
6	WBA7J22020G497013
7	WBA7J22040G497014
8	WBA7J22040G497031
9	WBA7J22060G497113
10	WBA7J22060G497466
11	WBA7J22090G497381
12	WBA7J220X0B219179
13	WBA7J220X0G497437
14	WBA7J220X0G497468
15	WBA7J220X0G497471
16	WBAJA92000BN71881
17	WBAJA92000BN72853
18	WBAJA92000BN74201
19	WBAJA92010BN71842
20	WBAJA92020BN72658
21	WBAJA92020BN72854
22	WBAJA92030BN71650
23	WBAJA92030BN71714
24	WBAJA92030BN74239
25	WBAJA92030G988530
26	WBAJA92040BN71379
27	WBAJA92050BN72878
28	WBAJA92060BN71741
29	WBAJA92060BN75515
30	WBAJA92060G758707
31	WBAJA92060G988649
32	WBAJA92060G988733
33	WBAJA92060G988747
34	WBAJA92070BN71683
35	WBAJA92070BN71764
36	WBAJA92070G988529
37	WBAJA92070G988627
38	WBAJA92080G988538
39	WBAJA92090BN71796
40	WBAJA92090BN72852
41	WBAJA920X0BN71631
42	WBAJA920X0BN71645
43	WBAJA920X0G988721