Recall Detail	
Ref No	**10001265**
Manufacturer	BMW
Vehicle Class	Motorcycles
Model/Type	S 1000 RR (K67) with A67, A67A10 engine
Dealer (phone no)	To Kwa Wan BMW-Customer Relation Department (31936688)
Subject	Program control units, check ignition steering lock function, replace ignition steering lock if necessary (0000510200)
Progress	**Running**
Affected Vehicle Identification Number (VIN)	List as below
Description of Defect, how it came to light, and possible consequences if ignored.	Among the affected vehicles, a component of the ignition steering lock may, under certain circumstances, become worn due to vibration. This can lead to poor electrical contact and result in ignition failure. If an ignition interruption occurs, it may cause the engine to stall.
Remedial Action	Program control units, check ignition steering lock function, replace ignition steering lock if necessary
Build Dates	25/06/2019 – 26/05/2026
Launch Date	19/08/2026
Tentative Date of Recall Completion	31/12/2027

1	WB10E2100LZJ96028
2	WB10E2101LZJ91713
3	WB10E2101LZJ92392
4	WB10E2102LZJ96368
5	WB10E2102M6E26156
6	WB10E2103LZJ92393
7	WB10E2103LZJ92880
8	WB10E2104LZJ92421
9	WB10E2105LZJ92394
10	WB10E2105LZJ92878
11	WB10E2105LZJ92881
12	WB10E2105N6F67305
13	WB10E2106LZJ93232
14	WB10E2107LZJ92879
15	WB10E2108LZJ92387
16	WB10E6100P6H00837
17	WB10E6101P6H97434
18	WB10E6102P6H96714
19	WB10E6103P6H21052
20	WB10E6104R6J24735
21	WB10E6105P6H29590
22	WB10E6105R6J24713
23	WB10E6105R6K11415
24	WB10E6106R6J20296
25	WB10E6107P6H21085
26	WB10E6108P6H37294
27	WB10E6109P6H29592
28	WB10E6109P6H96712
29	WB10E6109R6J21359
30	WB10P2100S6L58038
31	WB10P2102T6M76528
32	WB10P2103S6L56994
33	WB10P2103S6L94080
34	WB10P2104S6K95624
35	WB10P2105S6L93884
36	WB10P2105T6M95333
37	WB10P2106S6L29854
38	WB10P2107T6N18255
39	WB10P2108S6L94575
40	WB10P2108T6M97626
41	WB10P210XS6L29856
42	WB10P210XT6N25636