Recall Detail	
Ref No	**10000342**
Manufacturer	Automobile Peugeot
Vehicle Class	Private Car
Model/Type	1007
Dealer (phone no)	Sime Darby Motor Services Limited (Tel:39138800)
Subject	Replacement of Fuel Pump Sensor Module
Progress	**Completed**
Affected Vehicle Identification Number (VIN)	
Description of Defect, how it came to light, and possible consequences if ignored.	The fuel return pipe on the pump sensor module could crack in the long term. This would then produce a fuel leak.
Remedial Action	To replace the vehicle fuel pump sensor module.
Build Dates	Year 2006 to 2007
Launch Date	1 March 2011
Tentative Date of Recall Completion	15 July 2014