Transport Department Notice

Temporary Traffic and Transport Arrangements on Fanling Highway

Notice is hereby given that to facilitate road works on Fanling Highway, the following temporary traffic and transport arrangements will be implemented from 01.00 a.m. to 05.30 a.m. daily on 10, 12, 13 and 18 November 2026:

(1) ROAD CLOSURE

The following road sections will be temporarily closed to all vehicular traffic:

i. The slip road leading from So Kwun Po Road southbound and Kai Leng roundabout to Fanling Highway southbound;
ii. The slip road leading from Jockey Club Road southbound to Fanling Highway southbound;
iii. The slip road leading from Pak Wo Road northbound to Fanling Highway southbound; and
iv. The road section of Fanling Highway southbound from its junction with Tai Tau Leng roundabout to a point about 300 metres south of its junction with Pak Wo Road (near Dawning Views) (except the slow lane of the road section between Tai Tau Leng roundabout and Kai Leng roundabout (Exit 8)).

(2) TRAFFIC DIVERSION

i. Vehicles on Fanling Highway southbound or So Kwun Po Road heading for Heung Yuen Wai Boundary Control Point will be diverted via Kai Leng roundabout, So Kwun Po Road northbound, Jockey Club Road southbound, roundabout, Sha Tau Kok Road northbound, roundabout and Heung Yuen Wai Highway northbound;
ii. Vehicles on Fanling Highway southbound or So Kwun Po Road heading for Tai Po and Kowloon will be diverted via Kai Leng roundabout, So Kwun Po Road northbound, Jockey Club Road southbound, Pak Wo Road southbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound;
iii. Vehicles on Pak Wo Road northbound near Dawning Views heading for Heung Yuen Wai Boundary Control Point will be diverted via Pak Wo Road northbound, Jockey Club road northbound, roundabout, Sha Tau Kok Road northbound, roundabout and Heung Yuen Wai Highway northbound;
iv. Vehicles on Pak Wo Road northbound near Dawning Views heading for Tai Po and Kowloon will be diverted via Pak Wo Road northbound, Jockey Club road northbound, roundabout, Jockey Club Road southbound, Pak Wo Road southbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound; and
v. Vehicles on Jockey Club Road southbound near Tong Hang Tsuen heading for Heung Yuen Wai Boundary Control Point will be diverted via Pak Wo Road southbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Fanling Highway northbound and Heung Yuen Wai Highway northbound.

(3) <u>PUBLIC TRANSPORT SERVICES ARRANGEMENTS</u>

In connection with the road closures, 4 bus routes and 2 green minibus routes will be diverted. The affected routes are:

KMB	277X (Lam Tin Station bound), 278X (Tsuen Wan bound) and W3 (West Kowloon Station bound)
LWB	N42A (Tung Chung bound)
Green minibus	501S (Kwun Tong bound) and 616S (Mong Kok bound)

The bus and green minibus operators will display notices to advise passengers of the changes.

Appropriate traffic signs will be erected on site to guide motorists. Motorists are advised to follow the instructions on site and drive in utmost care.

TSE Wing-yee, Winnie *Commissioner for Transport*