Recall Detail

Ref No	**10000780**
Manufacturer	AUDI
Vehicle Class	Private Car
Model/Type	A4 (8K) / A5 (8T) / A6 (4G)
Dealer (phone no)	Premium Motors Ltd (3465 0000)
Subject	Replacing additional coolant pump
Progress	**Running**
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	On Audi vehicles with 2.0 ltr. TFSI engine manufactured within a specific period, it is possible that moisture may enter the electronic components and cause the overheating and failure of the additional coolant pump. As a result, localised smoulder damage cannot be ruled out. In individual cases, this may cause the vehicle to catch fire.
Remedial Action	The additional coolant pump must be replaced on the affected vehicles. A software update of the engine control unit must be carried out in addition.
Build Dates	Model Year: 2012 - 2014
Launch Date	13 Jun 2018
Tentative Date of Recall Completion	13 Jun 2019

1	WAUZZZ8T2CA024392
2	WAUZZZ8T7CA030012
3	WAUZZZ4G1DN152321
4	WAUZZZ8K4DA012740
5	WAUZZZ8K5DA014948
6	WAUZZZ8K2DA210989
7	WAUZZZ4G5EN016548
8	WAUZZZ4G0EN063227
9	WAUZZZ4G0EN097989
10	WAUZZZ4G5EN105195