Recall Detail

Ref No	**10000949**
Manufacturer	Honda
Vehicle Class	Private Car
Model/Type	STEPWGN RP1 & RP3
Dealer (phone no)	22168183
Subject	Replace Seat Belt Kit
Progress	**Running**
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The rear seat belt assemblies installed on affected vehicles have dual locking mechanisms that operate independently of one another to lock the seat belt: the vehicle sensor, which engages during vehicle deceleration, and the webbing sensor, which engages during rapid seat belt extension. Due to incorrect manufacturing of the rear seat belt assembly, the webbing sensor in the assembly could become inoperative and, if the vehicle sensor fails to engage during a crash, proper restraint may not be provided to a belted occupant, increasing the risk of an injury.
Remedial Action	Replace Seat Belt Kit
Build Dates	2020
Launch Date	06 JUL 2020
Tentative Date of Recall Completion	06 JUL 2027

JHMRP1850LC200010	JHMRP3870LC200138
JHMRP1850LC200011	JHMRP3870LC200139
JHMRP1850LC200012	JHMRP3870LC200140
JHMRP1850LC200013	JHMRP3870LC200141
JHMRP1850LC200014	JHMRP3870LC200142
JHMRP1850LC200015	JHMRP3870LC200143
JHMRP1850LC200016	JHMRP3870LC200144
JHMRP1850LC200017	JHMRP3870LC200145
JHMRP1850LC200018	JHMRP3870LC200146
JHMRP3870LC200130	JHMRP3870LC200147
JHMRP3870LC200131	JHMRP3870LC200148
JHMRP3870LC200132	JHMRP3870LC200149
JHMRP3870LC200133	JHMRP3870LC200151
JHMRP3870LC200134	JHMRP3870LC200152
JHMRP3870LC200135	JHMRP3870LC200153
JHMRP3870LC200136	JHMRP3870LC200154
JHMRP3870LC200137	JHMRP3870LC200155

JHMRP3870LC200156
JHMRP3870LC200157
JHMRP3870LC200158
JHMRP3870LC200159
JHMRP3870LC200160
JHMRP3870LC200161
JHMRP3870LC200162
JHMRP3870LC200163
JHMRP3870LC200164
JHMRP3870LC200165
JHMRP3870LC200166
JHMRP3870LC200167
JHMRP3870LC200168
JHMRP3870LC200169
JHMRP3870LC200170
JHMRP3870LC200171
JHMRP3870LC200172