Recall Detail	
Ref No	**10001248**
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	316ti, 323Ci, 330Ci (E46) with M52 TU , M54, N42 engine
Dealer (phone no)	To Kwa Wan BMW-Customer Relation Department (31936688)
Subject	Check the driver's airbag, replace if necessary (0032930200)
Progress	**Running**
Affected Vehicle Identification Number (VIN)	List as below
Description of Defect, how it came to light, and possible consequences if ignored.	Driver’s airbag – It’s gas generator, in case if this is exposed to high absolute air humidity for a period of years and/or there are quality deficiencies in the production of the gas generator. When the driver’s airbag is triggered in the regular fashion, this may result in high internal pressure in the gas generator. In unfavorable cases, the gas generator may split and metal parts may escape from the airbag.
Remedial Action	Check the driver's airbag, replace if necessary
Build Dates	20/03/2000 – 19/10/2001
Launch Date	11/10/2019
Tentative Date of Recall Completion	31/12/2030

1	WBAAT52030AF67836
2	WBABR32000EG07015
3	WBABR32000EG07094
4	WBABR32000EG07161
5	WBABR32000EG07256
6	WBABR32000EG07497
7	WBABR32010EG07282
8	WBABR32010EG07315
9	WBABR32010EG07492
10	WBABR32020EG07095
11	WBABR32020EG07100
12	WBABR32020EG07260
13	WBABR32030EG07350
14	WBABR32040EG07258
15	WBABR32040EG07275
16	WBABR32050EG07091
17	WBABR32050EG07107
18	WBABR32060EG07097
19	WBABR32060EG07102
20	WBABR32060EG07276
21	WBABR32070EG07092
22	WBABR32070EG07318
23	WBABR32070EG07481
24	WBABR32080EG07098
25	WBABR32080EG07277
26	WBABR32080EG07344
27	WBABR32090EG07093
28	WBABR32090EG07353
29	WBABR32090EG07420
30	WBABR32090EG07482
31	WBABR320X0EG07474
32	WBABS520X0EH92027