Recall Detail	
Ref No	**10001263**
Manufacturer	Hino
Vehicle Class	Light Goods Vehicle
Model/Type	Hino 300 Series XZU605R-WKMMV3, XKU710R-WKVQV3, XKU720R-WKVTV3 XZC710R-WKFQW3, XZC710R-WKTQV3, XZC710R-ZKFQW3 XZC720R-WKFQW3, XZC720R-WKFTW3, XZC720R-WKTQV3 XZC720R-WKTSV3, XZC720R-ZKTQV3, XZC740R-WKFTW3 XZC740R-WKTSV3, XZC740R-ZKFTW3, XZC740R-ZKTSV3
Dealer (phone no)	Crown Motors Limited (Tel: 2841 8520/ 2828 4545)
Subject	Inspect and re-tighten spare tire carrier bracket (H12)
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to inappropriate method of bolt tightening during installation of the carrier bracket of spare tire hung on the rear overhang, the tightening torque may not be adequate. Therefore, if the vehicle continues to operate with such condition, the bolts may loosen by vibration of the vehicle's operation, in the worst case, it may cause fall of the spare tire with the carrier bracket.
Remedial Action	Replace or re-tighten spare tire carrier bracket
Build Dates	September 2023 – January 2025
Launch Date	April 2025
Tentative Date of Recall Completion	31 December 2027

1	JHHUEV1F00K004733	55	JHHYEW1F80K005961	109	JHHYEV1F20K006145
2	JHHUEV1F20K004734	56	JHHYEV1F50K005958	110	JHHLEV1F60K006143
3	JHHUEV1F40K004735	57	JHHUEV1F70K004941	111	JHHYEV5F30K006150
4	JHHLEV1F30K005757	58	JHHUEV1F20K004944	112	JHHLEV1F50K006148
5	JHHLEV1F50K005758	59	JHHLEV1F10K005966	113	JHHPEV5F60K001133
6	JHHLEV1F70K005759	60	JHHUEV1F60K004946	114	JHHLEV1F40K006156
7	JHHLEV1F30K005760	61	JHHYEV1F20K005979	115	JHHLEV1F60K006157
8	JHHLEV1F50K005761	62	JHHLEV1F90K005987	116	JHHLEV1FX0K006162
9	JHHLEV1F70K005762	63	JHHYEV5F00K005991	117	JHHYEV5F50K006165
10	JHHLEV1F90K005763	64	JHHYEV1F40K005997	118	JHHLEV1F00K006168
11	JHHLEV1F20K005765	65	JHHUEV1F40K004959	119	JHHYEV1F10K006170
12	JHHLEV1F40K005766	66	JHHLEV1F00K006008	120	JHHLEV1F20K006172
13	JHHLEV1F60K005767	67	JHHYEV1F10K006010	121	JHHACV3G40K007942
14	JHHLEV1FX0K005769	68	JHHLEV1FX0K006016	122	JHHYEV1F40K006177
15	JHHLEV1F60K005770	69	JHHUEV1F30K004970	123	JHHPEV5F80K001134

16	JHHLEV1F00K005778	70	JHHUEV1F00K004974	124	JHHLEV1F60K006188
17	JHHLEV1F20K005779	71	JHHYEW1F70K006034	125	JHHYEV1F20K006193
18	JHHXEW2F60K001126	72	JHHYEV1F80K006036	126	JHHLEV1F80K006192
19	JHHLEV1F50K005811	73	JHHYEV1F50K006043	127	JHHLEV1F90K006198
20	JHHLEV1F00K005814	74	JHHLEV1F80K006046	128	JHHYEW2F40K006202
21	JHHLEV1FX0K005819	75	JHHUEV1F30K004984	129	JHHYEV1F90K006207
22	JHHLEV1F40K005833	76	JHHLEV1F00K006056	130	JHHLEV1F80K006208
23	JHHLEV1F60K005834	77	JHHYEV1F70K006061	131	JHHUEW1F90K005076
24	JHHPEV5F00K001127	78	JHHUEV1F20K004989	132	JHHYEW1F60K006218
25	JHHMEW1F00K004849	79	JHHUEV1F00K004991	133	JHHPEW2F70K001135
26	JHHACV3G20K007731	80	JHHYEV1F10K006069	134	JHHXEW2F90K001136
27	JHHACV3G30K007754	81	JHHYEV1F10K006072	135	JHHACV3G70K007949
28	JHHACV3G10K007770	82	JHHUEV1FX0K004996	136	JHHUEW1F30K005137
29	JHHACV3G70K007790	83	JHHXEV5F20K001131	137	JHHYEW1F50K006291
30	JHHYEV1F10K005875	84	JHHYEV1F20K006081	138	JHHPEW2F00K001137
31	JHHACV3G20K007793	85	JHHUEV1F10K005003	139	JHHACV3G70K007952
32	JHHUEV1F90K004892	86	JHHMEW1F60K005004	140	JHHXEW2F40K001139
33	JHHUEV1F60K004896	87	JHHYEW1F40K006086	141	JHHPEW2F20K001138
34	JHHLEV1F30K005886	88	JHHUEW1F10K005007	142	JHHYEW2F90K006311
35	JHHUEV1F10K004899	89	JHHYEV1F50K006091	143	JHHACV3G80K007958
36	JHHMEW1F20K004898	90	JHHUEV1F40K005013	144	JHHACV3G60K007960
37	JHHUEV1F80K004902	91	JHHACV3G00K007906	145	JHHXEW2F00K001140
38	JHHYEV1F00K005897	92	JHHYEV1F80K006098	146	JHHUEW1F40K005258
39	JHHUEV1F10K004904	93	JHHUEV1FX0K005016	147	JHHMEW1F90K005272
40	JHHUEV1F50K004906	94	JHHYEV1F60K006102	148	JHHYEW1F00K006442
41	JHHPEW2FX0K001128	95	JHHLEV1F90K006105	149	JHHYEW2F90K006468
42	JHHUEV1F70K004910	96	JHHACV3G30K007916	150	JHHMEW1F50K005334
43	JHHLEV1F00K005912	97	JHHUEV1F10K005020	151	JHHUNV1F50K004582
44	JHHLEV1F30K005919	98	JHHYEV1F00K006113	152	JHHPEW2F20K001141
45	JHHUEW1F40K004918	99	JHHUEV1F20K005026	153	JHHXEW2F40K001142
46	JHHLEV1F70K005924	100	JHHLEV1F90K006119	154	JHHLEV1F80K006483
47	JHHUEW1F40K004921	101	JHHYEV1F70K006125	155	JHHACV3G20K007972
48	JHHXEW2F10K001129	102	JHHLEV1F00K006123	156	JHHPEW2F60K001143
49	JHHMEW1F10K004925	103	JHHLEV1FX0K006128	157	JHHXEW2F80K001144
50	JHHYEV1F60K005936	104	JHHPEV5F40K001132	158	JHHLEV1FX0K006484
51	JHHXEW2F80K001130	105	JHHACV3GX0K007931	159	JHHUEW1F70K005335
52	JHHYEV1F10K005939	106	JHHUEW1F10K005038	160	JHHUEW1F90K005336
53	JHHYEV1F70K005945	107	JHHYEV5F90K006136	161	JHHYNV2F20K001624
54	JHHLEV1F50K005954	108	JHHLEV1F40K006139	162	JHHMEW1F00K005337