

Transport Department Notice

Temporary Traffic and Transport Arrangements on Fanling Highway

Notice is hereby given that to facilitate road works on Fanling Highway, the following temporary traffic and transport arrangements will be implemented from 01.00 a.m. to 05.30 a.m. daily on 5, 14 and 18 November 2025:

(1) ROAD CLOSURE

The following road sections will be temporarily closed to all vehicular traffic:

- i. The slip road leading from So Kwun Po Road southbound and Kai Leng roundabout to Fanling Highway southbound;
- ii. The slip road leading from Jockey Club Road southbound to Fanling Highway southbound;
- iii. The slip road leading from Pak Wo Road northbound to Fanling Highway southbound; and
- iv. The road section of Fanling Highway southbound from its junction with Tai Tau Leng roundabout to a point about 300 metres south of its junction with Pak Wo Road (near Dawning Views) (except the slow lane of the road section between Tai Tau Leng roundabout and Kai Leng roundabout (Exit 8)).

(2) TRAFFIC DIVERSION

- i. Vehicles on Fanling Highway southbound or So Kwun Po Road heading for Heung Yuen Wai Boundary Control Point will be diverted via Kai Leng roundabout, So Kwun Po Road northbound, Jockey Club Road southbound, roundabout, Sha Tau Kok Road northbound, roundabout and Heung Yuen Wai Highway northbound;
- ii. Vehicles on Fanling Highway southbound or So Kwun Po Road heading for Tai Po and Kowloon will be diverted via Kai Leng roundabout, So Kwun Po Road northbound, Jockey Club Road southbound, Pak Wo Road southbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound;
- iii. Vehicles on Pak Wo Road northbound near Dawning Views heading for Heung Yuen Wai Boundary Control Point will be diverted via Pak Wo Road northbound, Jockey Club road northbound, roundabout, Sha Tau Kok Road northbound, roundabout and Heung Yuen Wai Highway northbound; and
- iv. Vehicles on Pak Wo Road northbound near Dawning Views heading for Tai Po and Kowloon will be diverted via Pak Wo Road northbound, Jockey Club road northbound, roundabout, Jockey Club Road southbound, Pak Wo Road southbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound.

(3) PUBLIC TRANSPORT SERVICES ARRANGEMENTS

(A) Franchised Bus Service

- i. KMB Route Nos. 277X (Lam Tin Station bound), 278X(Tsuen Wan bound) and W3 (West Kowloon Station bound) will be diverted via Wah Ming Road southbound, Wo Hing Road

northbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound, and resume their normal routing. The en-route stop at Fanling Highway Bus-Bus Interchange will be suspended; and

- ii. LWB Route No. N42A (Tung Chung bound) will be diverted via Kai Leng roundabout, Pak Wo Road eastbound, Wah Ming Road southbound, Wo Hing Road northbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound, and resume its normal routing.

(B) Green Minibus Service

- i. New Territories GMB Route No.501S (Kwun Tong bound) will be diverted via Pak Wo road northbound, Jockey Club road northbound, roundabout, Jockey Club Road southbound, Pak Wo Road southbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound and Tai Po Road-Tai Wo southbound, and resume its normal routing; and
- ii. New Territories GMB Route No. 616S (Mong Kok bound) will be diverted via Fanling Highway southbound, So Kwun Po Road northbound, Jockey Club Road southbound, Pak Wo Road southbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound, and resume its normal routing.

Appropriate traffic signs will be erected on site to guide motorists. Motorists are advised to follow the instructions on site and drive in utmost care.

LEE Chung-yan, Angela *Commissioner for Transport*