Traffic Advice

<u>Temporary Traffic and Transport Arrangements on</u> <u>Cheung Tsing Highway and North West Tsing Yi Interchange</u>

To facilitate road works, motorist are advised that following temporary traffic and transport arrangements will be implemented on Cheung Tsing Highway and North West Tsing Yi Interchange during the time specified below:

Date and Time	Traffic and Transport Arrangements
From 1.00 am to 6.00 am on 3 July 2025	I. Road Closure Part of the traffic lanes of Cheung Tsing Highway northbound between Kam Chuk Kok and Tsing Yi North West Interchange will be temporarily closed. II. Temporary Speed Limit The above road section will be temporarily subject to a speed limit of 50 kilometres per hour.
From 1.00 am to 5.30 am on 4 July 2025	I. Road Closure The slip road leading from Tsing Yi North West Interchange northbound to Lantau Island will be temporarily closed. II. Temporary Speed Limit The road section between Cheung Tsing Highway northbound (near Kam Chuk Kok) and the slip road leading from Tsing Yi North West Interchange northbound to Lantau Link will be temporarily subject to a speed limit of 50 kilometres per hour. III. Traffic Diversion Affected vehicles on Tsing Yi North West Interchange northbound heading for Lantau Island will be diverted via the slip road leading from Tsing Yi North West Interchange northbound to View Point and Lantau Link Lower Deck (Airport bound) (except those driving vehicles carrying dangerous goods belonging to Category 1, 2, 3 or 3A). Vehicles carrying dangerous goods belonging to Category 1, 2, 3 or 3A will be diverted via the slip road leading from Tsing Yi North West Interchange northbound, Tsing Yi North West Interchange southbound, Tsing Yi North West Interchange (the slip road leading to Lantau Island) and Lautau Link Upper Deck (Airport bound). IV. Public Transport Arrangements The following bus and Residents' Service routes will be temporarily diverted via the slip road leading from Tsing Yi North West Interchange northbound to View Point and Lantau Link Lower Deck (Airport bound) before resuming its normal routing:

LWB Route Nos. NA30, NA31, NA32, NA40, NA41, NA47 and N31, CTB Route Nos. N11, N21, N21A, N23, N26, N29, NA12, NA20, NA21 and NA29 (Airport bound) and Residents' Services Route Nos. NR331 and NR331S (Ma Wan bound).

I. Road Closure

- (i) Parts of the traffic lanes of Cheung Tsing Highway southbound between Kam Chuk Kok and the western entrance of Cheung Tsing Tunnel;
- (ii) parts of the traffic lanes of Cheung Tsing Highway northbound between the western exit of Cheung Tsing Tunnel and Kam Chuk Kok; and
- (iii) the slip road leading from Tsing Yi North West Interchange northbound to Tuen Mun and Yuen Long will be temporarily closed.

II. Temporary Speed Limit

- (i) The road section between Cheung Tsing Highway (near Kam Chuk Kok) and Cheung Tsing Highway (near the western entrance of Cheung Tsing Tunnel);
- (ii) the road section between Cheung Tsing Highway (near the western exit of Cheung Tsing Tunnel) and Cheung Tsing Highway (near Kam Chuk Kok); and

From 00.00 midnight to 5.30 am daily on 8, 10 and 12 July 2025

(iii) the slip road leading from Tsing Yi North West Interchange northbound to View Point will be temporarily subject to a speed limit of 50 kilometres per hour.

III. Traffic Arrangements on Cheung Tsing Tunnel

The Kowloon bound tube of Cheung Tsing Tunnel will be temporarily closed. One-tube-two-way operation will be implemented in Airport bound tube.

IV. Traffic Diversion

Affected vehicles on Tsing Yi North West Interchange northbound heading for Tuen Mun and Yuen Long will be diverted via the slip road leading from Tsing Yi North West Interchange northbound to View Point, the roundabout near Tsing Yi Administration Building, Tsing Yi North West Interchange northbound and Tsing Long Highway northbound.

V. Public Transport Arrangements

The following bus routes will be temporarily diverted via the slip road leading from Tsing Yi North West Interchange northbound to View Point, the roundabout near Tsing Yi Administration Building and Tsing Yi North West Interchange northbound before resuming its normal routing:

KMB Route Nos. 61X, 62X, 68E, 258D, 259D, 260X, 268C, 269B, 269C and Cross Harbour Route Nos. 952, 960, 961, 962X, 967X, 968, 960, No. 2000, No. 2001, No. 2
969, N952, N960, N962 and N969 (Tuen Mun and Yuen Long bound).

Motorists are advised to drive with care and patience. Appropriate traffic signs will be provided on site to guide motorists.