

TRAFFIC ADVICE

Temporary Traffic and Transport Arrangements on Lin Tak Road and Tseung Kwan O Road, Kwun Tong

Motorists are advised that to facilitate construction works, the following temporary traffic and transport arrangements will be implemented in Kwun Tong from 1.00 am to 5.30 am on 4 and 11 January 2026.

(1) Lane Closure

The following traffic lanes will be temporarily closed to all vehicular traffic:

- (a) The slow lane of Tseung Kwan O Tunnel Road westbound from a point about 1000 metres west from the exit of Tseung Kwan O Tunnel westbound to its junction with Tseung Kwan O Road;
- (b) The fast lane of Lin Tak Road southbound from its junction with Tseung Kwan O Road to a point about 40 metres north of the same junction; and
- (c) The slow lane of Tseung Kwan O Road westbound of about 40 metres in length near Tseung Kwan O Tunnel Bus-Bus Interchange.

(2) Road Closure

The following road sections will be temporarily closed to all vehicular traffic:

- (a) Tseung Kwan O Road westbound from its junction with the exit of Tseung Kwan O Tunnel westbound to a point about 250 metres west of the same junction; and
- (b) A section of Tseung Kwan O Road westbound leading from Lin Tak Road southbound.

(3) Banning of Turning Movement

- (a) All vehicles will be temporarily prohibited from making right turn from Lin Tak Road southbound onto Tseung Kwan O Road westbound; and
- (b) All vehicles will be temporarily prohibited from making right turn from Tseung Kwan O Road eastbound onto Tseung Kwan O Road westbound outside Kwun Tong Discipline Service Quarters.

(4) Traffic Diversion

- (a) Affected vehicles on Tseung Kwan O Road eastbound heading to Tseung Kwan O Road westbound will be diverted via Tseung Kwan O Road eastbound, Lin Tak Road southbound, Pik Wan Road roundabout, Lin Tak Road northbound and Tseung Kwan O Road westbound;

- (b) Affected vehicles on Tseung Kwan O Road westbound heading to Lam Tin / Kai Tin Road will be diverted via Tseung Kwan O Road westbound, Lei Yue Mun Road eastbound, Kai Tin Road roundabout and Kai Tin Road northbound; and
- (c) Affected vehicles on Tseung Kwan O Road westbound heading to Kwun Tong Bypass will be diverted via Tseung Kwan O Road westbound, Lei Yue Mun Road eastbound, Kai Tin Road roundabout, Lei Yue Mun Road westbound, Wai Fat Road southbound and Kwun Tong Bypass westbound.

(5) Public Transport Arrangements

- (a) The bus stops at the Kowloon bound of Tseung Kwan O Tunnel Bus-Bus Interchange will be temporarily relocated about 150 metres eastward;
- (b) KMB Route No. 213M (Lam Tin bound) and XHT Route No. N691 (Hong Kong Island bound) will be diverted via Lin Tak Road southbound, Tak Tin Street westbound, Kai Tin Road northbound and Tseung Kwan O Road westbound and then resume original routeing;
- (c) KMB Route No. 98A (Kwun Tong bound) will be diverted via Lin Tak Road southbound, Tak Tin Street westbound, Kai Tin Road northbound, Tseung Kwan O Road westbound, Lei Yue Mun Road eastbound, Kai Tin Road Roundabout and Lei Yue Mun Road westbound and then resume original routeing;
- (d) KMB Route No. 293S (Mei Foo bound) will be diverted via Lin Tak Road southbound, Tak Tin Street westbound, Kai Tin Road northbound, Tseung Kwan O Road westbound, Lei Yue Mun Road eastbound, Kai Tin Road roundabout, Lei Yue Mun Road westbound, Wai Fat Road southbound and Kwun Tong Bypass westbound and then resume original routeing;
- (e) CTB Route Nos. 796S (Ngau Tau Kok bound), NA29 (Hong Kong Zhuhai Macao Bridge bound) and N796 (Mongkok bound) and New Territories GMB Route No. 102S (San Po Kong bound) will be diverted via Tseung Kwan O Road westbound, Lei Yue Mun Road eastbound, Kai Tin Road roundabout and Lei Yue Mun Road westbound and then resume original routeing; and
- (f) CTB Route No. N29 (Tung Chung bound) will be diverted via Tseung Kwan O Road westbound, Lei Yue Mun Road eastbound, Kai Tin Road roundabout, Kai Tin Road northbound, Tak Tin Street roundabout and Kai Tin Road southbound and then resume original routeing.

Appropriate traffic signs will be erected on site to guide motorists. Motorists are advised to observe the instruction and drive with utmost care. Notices will also be displayed by public transport operators to advise passengers of the above arrangement.