

Transport Department Notice

Temporary Traffic Arrangements on Fanling Highway, Tai Po and North District

Notice is hereby given that to facilitate the road works on Fanling Highway, the following temporary traffic and transport arrangements will be implemented from 00.30 am to 05.30am on 17 August 2019:

(I) ROAD CLOSURE

The following road sections will be temporarily closed to all vehicular traffic:

1. The section of Fanling Highway southbound between So Kwun Po Road roundabout and Hong Lok Yuen Road;
2. The slip road leading from So Kwun Po Road to Fanling Highway southbound;
3. The slip road leading from Jockey Club Road to Fanling Highway southbound; and
4. The slip road leading from Pak Wo Road to Fanling Highway southbound.

(II) TRAFFIC DIVERSION

1. Vehicles on Heung Yuen Wai Highway southbound heading for Kau Lung Hang will be diverted via Fanling Highway northbound, slip road (exit 7B), Pak Wo Road southbound, Wah Ming Road southbound, roundabout, Wo Hing Road eastbound, Tai Wo Service Road West southbound, slip road and Tai Wo Service Road East northbound;
2. Vehicles on Heung Yuen Wai Highway southbound heading for Tai Po and Kowloon will be diverted via Fanling Highway northbound, slip road (exit 7B), Pak Wo Road southbound, Wah Ming Road southbound, roundabout, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Tai Po Road – Tai Wo southbound, Lam Kam Road Interchange and Tolo Highway southbound;
3. Vehicles on Fanling Highway southbound or So Kwun Po Road eastbound or westbound heading for Heung Yuen Wai will be diverted via So Kwun Po Road roundabout, So Kwun Po Road eastbound, Jockey Club Road southbound, Pak Wo Road southbound, unnamed road eastbound, Tai Wo Service Road West southbound, Fanling Highway northbound, slip road and Heung Yuen Wai Highway northbound;
4. Vehicles on Fanling Highway southbound or So Kwun Po Road eastbound or westbound heading for Tai Po and Kowloon will be diverted via So Kwun Po Road roundabout, So Kwun Po Road eastbound, Jockey Club Road southbound, Pak Wo Road southbound, unnamed road eastbound, Tai Wo Service Road West southbound, Tai Po Road – Tai Wo southbound, Lam Kam Road Interchange and Tolo Highway southbound;
5. Vehicles on Fanling Highway southbound or So Kwun Po Road eastbound or westbound heading for Kau Lung Hang will be diverted via So Kwun Po Road roundabout, So Kwun Po Road eastbound, Jockey Club Road southbound, Pak Wo Road southbound, unnamed road

- eastbound, Tai Wo Service Road West southbound, slip road and Tai Wo Service Road East northbound;
6. Vehicles on Sha Tau Kok Road (Lung Yeuk Tau) eastbound or westbound heading for Kau Lung Hang will be diverted via Sha Tau Kok Road – Lung Yeuk Tau roundabout, Jockey Club Road southbound, Pak Wo Road southbound, unnamed road eastbound, Tai Wo Service Road West southbound, slip road and Tai Wo Service Road East northbound;
 7. Vehicles on Sha Tau Kok Road (Lung Yeuk Tau) eastbound or westbound heading for Tai Po and Kowloon will be diverted via Sha Tau Kok Road – Lung Yeuk Tau roundabout, Jockey Club Road southbound, Pak Wo Road southbound, unnamed road eastbound, Tai Wo Service Road West southbound, Tai Po Road – Tai Wo southbound, Lam Kam Road Interchange and Tolo Highway southbound;
 8. Vehicles on Pak Wo Road eastbound heading for Heung Yuen Wai will be diverted via Jockey Club Road northbound, Sha Tau Kok Road – Lung Yeuk Tau roundabout, Jockey Club Road southbound, Pak Wo Road southbound, unnamed road eastbound, Tai Wo Service Road West southbound, Fanling Highway northbound, slip road and Heung Yuen Wai Highway northbound;
 9. Vehicles on Pak Wo Road eastbound heading for Kau Lung Hang will be diverted via Jockey Club Road northbound, Sha Tau Kok Road – Lung Yeuk Tau roundabout, Jockey Club Road southbound, Pak Wo Road southbound, unnamed road eastbound, Tai Wo Service Road West southbound, slip road and Tai Wo Service Road East northbound;
 10. Vehicles on Pak Wo Road eastbound heading for Tai Po and Kowloon will be diverted via Jockey Club Road northbound, Sha Tau Kok Road – Lung Yeuk Tau roundabout, Jockey Club Road southbound, Pak Wo Road southbound, unnamed road eastbound, Tai Wo Service Road West southbound, Tai Po Road – Tai Wo southbound, Lam Kam Road Interchange and Tolo Highway southbound; and
 11. Vehicles on Kau Lung Hang Lo Wai or Tai Wo Service Road East southbound heading for Tai Po and Kowloon will be diverted via Tai Wo Service Road East southbound, slip road, Tai Wo Service Road West southbound, Tai Po Road – Tai Wo southbound, Lam Kam Road Interchange and Tolo Highway southbound.

PUBLIC TRANSPORT SERVICES ARRANGEMENTS

(A) Franchised Bus Services

1. KMB route nos. 277X and 278X on their journey to Lam Tin and Tsuen Wan respectively will be diverted via Wah Ming Road southbound, roundabout, Wo Hing Road eastbound, Tai Wo Service Road West southbound and Lam Kam Road Interchange before resuming its original routing. The en-route stops of the above routes at the bus-bus interchange at Fanling Highway will be suspended; and
2. LWB route nos. N42A and N42P on their journey to Tung Chung and Airport respectively will be diverted via San Wan Road southbound, Jockey Club Road southbound, Pak Wo Road southbound, the unnamed road eastbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound and Lam Kam Road Interchange before resuming its original routing.

(B) Green Minibus Services

1. NT GMB route no. 501S on its journey to Kwun Tong will be diverted via Jockey Club Road northbound, Sha Tau Kok Road – Lung Yeuk Tau roundabout, Jockey Club Road southbound, Pak Wo Road southbound, the unnamed road eastbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound before resuming its original routing; and
2. NT GMB route no. 616S on its journey to Mong Kok will be diverted via So Kwun Po Road roundabout, So Kwun Po Road eastbound, Jockey Club Road southbound, Pak Wo Road southbound, the unnamed road eastbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound before resuming its original routing.

Appropriate traffic aids will be erected on site. Motorists are advised to follow the instructions on site and drive in utmost care.

CHAN Mable *Commissioner for Transport*