

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey RB1

項目 Subject: 更換改良電油泵繼電器

Replace fuel pump relay

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

1	JHMRB18205C200156	31	JHMRB18605C200887
2	JHMRB18205C200157	32	JHMRB18605C200888
3	JHMRB18205C200158	33	JHMRB18605C200889
4	JHMRB18205C200159	34	JHMRB18605C200890
5	JHMRB18205C200296	35	JHMRB18605C200891
6	JHMRB18205C200299	36	JHMRB18605C201296
7	JHMRB18205C200300	37	JHMRB18605C201297
8	JHMRB18205C200309	38	JHMRB18605C201300
9	JHMRB18205C200310	39	JHMRB18605C201301
10	JHMRB18205C200558	40	JHMRB18605C201302
11	JHMRB18205C203345	41	JHMRB18605C201314
12	JHMRB18205C203346	42	JHMRB18605C201315
13	JHMRB18205C203347	43	JHMRB18605C201316
14	JHMRB18205C203348	44	JHMRB18605C201317
15	JHMRB18205C203349	45	JHMRB18605C201318
16	JHMRB18605C200292	46	JHMRB18605C201327
17	JHMRB18605C200293	47	JHMRB18605C201328
18	JHMRB18605C200294	48	JHMRB18605C201329
19	JHMRB18605C200295	49	JHMRB18605C201330
20	JHMRB18605C200418	50	JHMRB18605C201331
21	JHMRB18605C200419	51	JHMRB18605C201337
22	JHMRB18605C200420	52	JHMRB18605C201338
23	JHMRB18605C200532	53	JHMRB18605C201339
24	JHMRB18605C200533	54	JHMRB18605C201340
25	JHMRB18605C200534	55	JHMRB18605C201341
26	JHMRB18605C200882	56	JHMRB18605C201711
27	JHMRB18605C200883	57	JHMRB18605C201712
28	JHMRB18605C200884	58	JHMRB18605C201713
29	JHMRB18605C200885	59	JHMRB18605C201714
30	JHMRB18605C200886	60	JHMRB18605C201715

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: Odyssey RB1

項目 Subject: 更換改良電油泵繼電器

Replace fuel pump relay

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

61	JHMRB18605C201716	91	JHMRB18605C202362
62	JHMRB18605C201717	92	JHMRB18605C202363
63	JHMRB18605C201718	93	JHMRB18605C202364
64	JHMRB18605C201719	94	JHMRB18605C202365
65	JHMRB18605C201720	95	JHMRB18605C202366
66	JHMRB18605C201949	96	JHMRB18605C202367
67	JHMRB18605C201950	97	JHMRB18605C202368
68	JHMRB18605C201952	98	JHMRB18605C202369
69	JHMRB18605C201953	99	JHMRB18605C202370
70	JHMRB18605C201954	100	JHMRB18605C202371
71	JHMRB18605C201965	101	JHMRB18605C202372
72	JHMRB18605C201966	102	JHMRB18605C202373
73	JHMRB18605C201967	103	JHMRB18605C202374
74	JHMRB18605C201973	104	JHMRB18605C202375
75	JHMRB18605C201974	105	JHMRB18605C202393
76	JHMRB18605C202283	106	JHMRB18605C202394
77	JHMRB18605C202284	107	JHMRB18605C202395
78	JHMRB18605C202285	108	JHMRB18605C202396
79	JHMRB18605C202286	109	JHMRB18605C202397
80	JHMRB18605C202287	110	JHMRB18605C202398
81	JHMRB18605C202288	111	JHMRB18605C202493
82	JHMRB18605C202289	112	JHMRB18605C202494
83	JHMRB18605C202290	113	JHMRB18605C202495
84	JHMRB18605C202291	114	JHMRB18605C202496
85	JHMRB18605C202292	115	JHMRB18605C202497
86	JHMRB18605C202293	116	JHMRB18605C202498
87	JHMRB18605C202354	117	JHMRB18605C202499
88	JHMRB18605C202355	118	JHMRB18605C202500
89	JHMRB18605C202356	119	JHMRB18605C202501
90	JHMRB18605C202361	120	JHMRB18605C202502

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda
型號 Model: Odyssey RB1
項目 Subject: 更換改良電油泵繼電器
Replace fuel pump relay

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

121	JHMRB18605C202754	151	JHMRB18605C203029
122	JHMRB18605C202755	152	JHMRB18605C203030
123	JHMRB18605C202756	153	JHMRB18605C203031
124	JHMRB18605C202757	154	JHMRB18605C203032
125	JHMRB18605C202758	155	JHMRB18605C203033
126	JHMRB18605C202759	156	JHMRB18605C203034
127	JHMRB18605C202762	157	JHMRB18605C203035
128	JHMRB18605C202763	158	JHMRB18605C203036
129	JHMRB18605C202764	159	JHMRB18605C203037
130	JHMRB18605C202765	160	JHMRB18605C203038
131	JHMRB18605C202766	161	JHMRB18605C203039
132	JHMRB18605C202775	162	JHMRB18605C203040
133	JHMRB18605C202776	163	JHMRB18605C203041
134	JHMRB18605C202777	164	JHMRB18605C203042
135	JHMRB18605C202778	165	JHMRB18605C203043
136	JHMRB18605C202785	166	JHMRB18605C203044
137	JHMRB18605C202786	167	JHMRB18605C203045
138	JHMRB18605C202787	168	JHMRB18605C203046
139	JHMRB18605C202788	169	JHMRB18605C203081
140	JHMRB18605C202801	170	JHMRB18605C203082
141	JHMRB18605C202993	171	JHMRB18605C203399
142	JHMRB18605C202994	172	JHMRB18605C203400
143	JHMRB18605C202995	173	JHMRB18605C203401
144	JHMRB18605C202996	174	JHMRB18605C203402
145	JHMRB18605C202997	175	JHMRB18605C203403
146	JHMRB18605C202998	176	JHMRB18605C203404
147	JHMRB18605C203001	177	JHMRB18605C203405
148	JHMRB18605C203026	178	JHMRB18605C203406
149	JHMRB18605C203027	179	JHMRB18605C203407
150	JHMRB18605C203028	180	JHMRB18605C203408

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda
型號 Model: Odyssey RB1
項目 Subject: 更換改良電油泵繼電器
Replace fuel pump relay

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

181	JHMRB18605C203409
182	JHMRB18605C203410
183	JHMRB18605C203411
184	JHMRB18605C203412
185	JHMRB18605C203413
186	JHMRB18605C203414
187	JHMRB18605C203415
188	JHMRB18605C203416
189	JHMRB18605C203417
190	JHMRB18605C203418
191	JHMRB18605C203419
192	JHMRB18605C203420
193	JHMRB18605C203421
194	JHMRB18605C203422
195	JHMRB18605C203423
196	JHMRB18605C203424
197	JHMRB18605C203425
198	JHMRB18605C203426
199	JHMRB18605C203427
200	JHMRB18605C203428