

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 賓利 Bentley

型號 Model: (1) Continental GT (2) Continental GT Speed
(3) Continental Flying Spur (4) Continental GTC

項目 Subject: 路面鹽侵蝕可能導致燃油過濾器泄漏

Fuel filter potential leak caused by road salt corrosion

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

1	SCBCE63WX4C020247	31	SCBCE63W85C024718
2	SCBCE63WX4C020278	32	SCBCE63W35C024786
3	SCBCE63W84C020618	33	SCBCE63W55C025440
4	SCBCE63W94C020823	34	SCBCE63W65C025575
5	SCBCE63W44C020860	35	SCBCE63W95C025814
6	SCBCE63W44C020910	36	SCBCE63W75C027786
7	SCBCE63W74C020948	37	SCBCE63W45C027843
8	SCBCE63W54C020981	38	SCBCE63W35C027865
9	SCBCE63W44C021023	39	SCBCE63W85C028106
10	SCBCE63W54C021080	40	SCBCE63W25C028473
11	SCBCE63W34C021241	41	SCBCE63W55C028757
12	SCBCE63W54C021290	42	SCBCE63W85C028851
13	SCBCE63W44C021300	43	SCBCE63W15C029372
14	SCBCE63W44C021345	44	SCBCE63WX5C029404
15	SCBCE63WX4C021821	45	SCBCE63W65C029481
16	SCBCE63W84C021865	46	SCBCE63W85C029496
17	SCBCE63W54C021936	47	SCBCE63W05C029508
18	SCBCE63W94C022006	48	SCBCE63W56C030669
19	SCBCE63W04C022041	49	SCBCE63W56C030705
20	SCBCE63W74C022313	50	SCBCE63WX6C030747
21	SCBCE63W74C022442	51	SCBBE53W36C031406
22	SCBCE63W44C022799	52	SCBBE53W56C031407
23	SCBCE63W04C022833	53	SCBBE53W56C031584
24	SCBCE63W34C022857	54	SCBBE53W76C031702
25	SCBCE63W94C023026	55	SCBBE53W96C031751
26	SCBCE63W84C023079	56	SCBBE53W46C032208
27	SCBCE63W34C023099	57	SCBBE53W36C032250
28	SCBCE63W84C023101	58	SCBBE53W16C032408
29	SCBCE63W05C024082	59	SCBBE53W66C032453
30	SCBCE63W55C024658	60	SCBBE53W86C032728

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 賓利 Bentley

型號 Model: (1) Continental GT (2) Continental GT Speed
(3) Continental Flying Spur (4) Continental GTC

項目 Subject: 路面鹽侵蝕可能導致燃油過濾器泄漏

Fuel filter potential leak caused by road salt corrosion

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

61	SCBBE53W16C032795	91	SCBBE53W16C039777
62	SCBBE53W26C033051	92	SCBCE63W47C041387
63	SCBBE53W36C033124	93	SCBCE63W67C041391
64	SCBCE63W16C033424	94	SCBBE53W97C041424
65	SCBBE53W36C033477	95	SCBCE63W27C041579
66	SCBBE53W36C033530	96	SCBBE53W17C042051
67	SCBCE63W76C033573	97	SCBBE53W57C042053
68	SCBBE53W76C033983	98	SCBBE53W47C042271
69	SCBBE53W66C034364	99	SCBBE53W57C042277
70	SCBBE53W36C035178	100	SCBBE53W07C042350
71	SCBBE53W46C035254	101	SCBCE63W57C042502
72	SCBBE53WX6C035310	102	SCBBE53W87C042550
73	SCBBE53W46C035318	103	SCBBE53W67C042563
74	SCBCE63W36C035319	104	SCBBE53W07C042915
75	SCBBE53WX6C035372	105	SCBBE53W67C043101
76	SCBBE53W26C035527	106	SCBBE53W57C043283
77	SCBBE53W46C035562	107	SCBCE63W77C043554
78	SCBBE53W96C035671	108	SCBCE63WX7C043984
79	SCBBE53W16C035731	109	SCBBE53W97C044033
80	SCBBE53W56C035747	110	SCBCE63W27C044594
81	SCBBE53W46C035755	111	SCBDE23W47C044917
82	SCBBE53W06C035932	112	SCBDE23W87C044919
83	SCBBE53W56C036655	113	SCBBE53WX7C045322
84	SCBBE53W66C036664	114	SCBCE63W77C045773
85	SCBBE53W16C036832	115	SCBBE53W07C046303
86	SCBBE53W16C037592	116	SCBDE23W27C046682
87	SCBBE53W66C037796	117	SCBBE53W57C046796
88	SCBBE53W46C039241	118	SCBCE63W87C046916
89	SCBBE53W36C039246	119	SCBDE23W67C047222
90	SCBBE53W36C039277	120	SCBBE53WX8C052160

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 賓利 Bentley

型 號 Model: (1) Continental GT (2) Continental GT Speed
(3) Continental Flying Spur (4) Continental GTC

項 目 Subject: 路面鹽侵蝕可能導致燃油過濾器泄漏

Fuel filter potential leak caused by road salt corrosion

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

121	SCBBE53W18C052192	151	SCBBE53W68C054598
122	SCBDE23W18C052250	152	SCBBE53W08C054628
123	SCBBE53W08C052345	153	SCBBE53W68C054746
124	SCBBE53W18C052421	154	SCBBE53W98C054823
125	SCBBE53W58C052485	155	SCBBE53W58C054902
126	SCBBE53W18C052774	156	SCBBE53W68C054911
127	SCBBE53WX8C052806	157	SCBCF63W98C054943
128	SCBBE53W58C052891	158	SCBDE23W28C055030
129	SCBBE53W98C052893	159	SCBBE53W68C055038
130	SCBBE53WX8C052935	160	SCBBE53W58C055077
131	SCBBE53W78C052990	161	SCBBE53WX8C055091
132	SCBBE53W88C053016	162	SCBBE53W48C055104
133	SCBBE53W98C053493	163	SCBBE53WX8C055124
134	SCBBE53W68C053497	164	SCBCF63W18C055200
135	SCBBE53W28C053609	165	SCBBE53WX8C055334
136	SCBBE53W08C053611	166	SCBBE53W38C055353
137	SCBBE53W48C053613	167	SCBBE53WX8C055477
138	SCBBE53W58C053670	168	SCBBE53W48C055524
139	SCBBE53W98C053672	169	SCBBE53WX8C055589
140	SCBCF63W08C053955	170	SCBBE53W58C055628
141	SCBCF63W28C053990	171	SCBCE63W18C055751
142	SCBCE63W98C054377	172	SCBBE53W88C055753
143	SCBCE63W78C054460	173	SCBDE23W38C055781
144	SCBCF63W48C054462	174	SCBDE23WX8C055891
145	SCBDE23W48C054493	175	SCBBE53W08C056072
146	SCBCF63W08C054507	176	SCBBE53W28C056123
147	SCBDE23W78C054519	177	SCBBE53W98C056152
148	SCBBE53W28C054548	178	SCBBE53W08C056203
149	SCBBE53W08C054564	179	SCBBE53WX8C056290
150	SCBBE53W88C054568	180	SCBBE53W68C056531

車輛安全召回資訊

Vehicle Safety Recall Information

製造商	Make:	賓利 Bentley	
型 號	Model:	(1) Continental GT	(2) Continental GT Speed
		(3) Continental Flying Spur	(4) Continental GTC
項 目	Subject:	路面鹽侵蝕可能導致燃油過濾器泄漏	
		Fuel filter potential leak caused by road salt corrosion	

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

181	SCBBE53W98C056569
182	SCBBE53W28C056574
183	SCBBE53W98C056605
184	SCBBE53W28C056607
185	SCBBE53W08C056640
186	SCBBE53W48C056723
187	SCBBE53W78C056750