

Recall Detail	
Ref No	10000284
Manufacturer	Jaguar
Vehicle Class	M1 – Private Car
Model/Type	XJ
Dealer (phone no.)	British Motors Limited (Tel: 2821 7100 or 2820 5150 / service@britishmotors.com.hk)
Subject	Under floor brake pipe corrosion
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	A review of vehicle build shows that a touch condition can exist between the under floor brake pipes and the NVH pad at the rear of the under floor undertray. Where a touch condition exists, water and dirt can collect and be held in contact with the pipes and their connectors reducing the corrosion life of the pipes accordingly. This can result in extended brake pedal travel and a simultaneous display of the 'fluid level low' warning light.
Remedial Action	Replace the brake pipes and connectors when necessary.
Build Dates	2003 to 2004
Launch Date	20 July 2009
Tentative Date of Recall Completion	31 December 2016

1	SAJAC72M04VG05542
2	SAJAC72M14VG06358
3	SAJAC72M44VG20576
4	SAJAC72M54VG26273
5	SAJAC72M64VG19865
6	SAJAC72M64VG20255
7	SAJAC72M74VG20264
8	SAJAC72N64RG00430
9	SAJAC72N74RG08410
10	SAJAC72N94RG07047