

Recall Detail

Ref No	10000375
Manufacturer	Rolls-Royce
Vehicle Class	Passenger Car
Model/Type	Ghost
Dealer (phone no)	31936999
Subject	Auxiliary water pump replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	Incorrect warning message "Engine Overheating" may appear in instrument, upgrade on related item is required.
Remedial Action	Replace auxiliary water pump
Build Dates	01-09-2009 – 01-10-2010
Launch Date	04/11/2011
Tentative Date of Recall Completion	31/05/2012

1	UH14631
2	UH14638
3	UH14639
4	UH14642
5	UH14647
6	UH14651
7	UH14653
8	UH14657
9	UH14658
10	UH14659
11	UH14661
12	UH14676
13	UH14686
14	UH14710
15	UH14735
16	UH14746
17	UH14747
18	UH14770
19	UH14785
20	UH14796
21	UH14797

22	UH14804
23	UH14808
24	UH14810
25	UH14818
26	UH14836
27	UH14837
28	UH14842
29	UH14843
30	UH14846
31	UH14847
32	UH14848
33	UH14849
34	UH14850