

Recall Detail	
Ref No	10000403
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	7 series (F03)
Dealer (phone no)	31936688
Subject	Replace the fuel filler pipe
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	Due to a manufacturing defect, the ventilation for the fuel tank may be fully or partially closed off in the area of the fuel filler pipe. The fuel tank may expand under high ambient temperatures when the ventilation is closed off. Scrapping of the universal shaft on the fuel tank cannot be ruled out.
Remedial Action	Replace the fuel filler pipe
Build Dates	09/2011
Launch Date	26/09/2012
Tentative Date of Recall Completion	31/03/2013

1	B590935
2	B590936
3	B590937
4	B590938