

Recall Detail

Ref No	10000406
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Prius
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Electrically Driven Water Pump
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to a possibility that the coil wire of the electric motor in the water pump of the hybrid system may have been scratched during the coiling manufacturing process. In this condition, the coil wire may corrode at the scratched portion, which may possibly cause the water pump to stop, leading to illumination of various warning lights. In limited instances, a short circuit may occur between adjacent coil wires, resulting in a blown fuse for the electric supply circuit, causing the hybrid system to stop while the vehicle is being driven.
Remedial Action	Inspect or replace the electrically driven water pump
Build Dates	June 2003 – April 2009
Launch Date	14 November 2012
Tentative Date of Recall Completion	December 2018

1	JTDKB20U303344356
2	JTDKB22U500117751
3	JTDKB20UX07777911
4	JTDKB20U107776825
5	JTDKB20UX07777116
6	JTDKB20U203364534
7	JTDKB22U300032973
8	JTDKB20U903133744
9	JTDKB20U907777088
10	JTDKB20U603298070
11	JTDKB20U807845638
12	JTDKB22U503059168
13	JTDKB20U607080669
14	JTDKB20U903309899
15	JTDKB20U803356938
16	JTDKB20U603364794
17	JTDKB20U903367091
18	JTDKB20U403369461
19	JTDKB20U303371153
20	JTDKB20U503372370

21	JTDKB20U503371753
22	JTDKB20U903372646
23	JTDKB20U807751694
24	JTDKB20U503377326
25	JTDKB20U203377302
26	JTDKB20U503377990
27	JTDKB20U107754761
28	JTDKB20U807683168
29	JTDKB22U403058867
30	JTDKB20U703289281
31	JTDKB20UX07859346
32	JTDKB20U103395158
33	JTDKB20U707779910
34	JTDKB20U903381105
35	JTDKB20U903311572
36	JTDKB20UX03469838
37	JTDKB20U103400889
38	JTDKB20UX07779755
39	JTDKB20U703312395
40	JTDKB22U903054569

41	JTDKB20U907683681
42	JTDKB20U703473068
43	JTDKB20U003448691
44	JTDKB20U103130482
45	JTDKB20U007793664
46	JTDKB20U303422862
47	JTDKB20UX07778489
48	JTDKB20U207703477
49	JTDKB22U200104620
50	JTDKB22U603040273
51	JTDKB22U100034107
52	JTDKB22U403062014
53	JTDKB22U900037773
54	JTDKB20UX07535281
55	JTDKB20U407845619
56	JTDKB22U603044341
57	JTDKB20U807670288
58	JTDKB20U303266435
59	JTDKB20U903278119
60	JTDKB22U400121631
61	JTDKB20UX07698643
62	JTDKB20U103317740
63	JTDKB20U203309954
64	JTDKB22U900036574
65	JTDKB20U003416517
66	JTDKB20U007788058
67	JTDKB20U903430173
68	JTDKB20U603430261
69	JTDKB20U807801378
70	JTDKB20U403461492
71	JTDKB20U407812846
72	JTDKB22U800047338
73	JTDKB20U507820633
74	JTDKB20U003462817
75	JTDKB20U607851566
76	JTDKB20U903235870
77	JTDKB20U803430908
78	JTDKB22U900034727
79	JTDKB20U707533813
80	JTDKB20U607776299
81	JTDKB22U300007636

82	JTDKB22U100031854
83	JTDKB22U900048496
84	JTDKB22UX00069101
85	JTDKB22UX00091308
86	JTDKB22U900090716
87	JTDKB22U500103476
88	JTDKB22U603016362
89	JTDKB22U303026637
90	JTDKB22U303037850
91	JTDKB22U303039372
92	JTDKB22U303069360
93	JTDKB22U703075002
94	JTDKB22UX03076550
95	JTDKB20U003155860
96	JTDKB20U907526992
97	JTDKB20U207607378
98	JTDKB20U303300406
99	JTDKB20U707712885
100	JTDKB20U007715482
101	JTDKB20U507717051
102	JTDKB20U403328991
103	JTDKB20U407764474
104	JTDKB20U503401818
105	JTDKB20U203423789
106	JTDKB20U107811895
107	JTDKB20U707820939
108	JTDKB20U803479624
109	JTDKB20U003497034