

Recall Detail

Ref No	10000410
Manufacturer	Volvo
Vehicle Class	Private Car
Model/Type	XC90 2.5T / XC90 T5
Dealer (phone no)	29273399
Subject	Replace the power steering gear valve housing internal pipe
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	It may result in a sudden drainage of power steering oil and a loss of power steering assistance
Remedial Action	Replace the power steering gear valve housing internal pipe
Build Dates	2010
Launch Date	2 January 2013
Tentative Date of Recall Completion	30 June 2013

1	YV1CZ5957A1554248
2	YV1CZ5957A1554250
3	YV1CZ5957A1556547
4	YV1CZ5957A1556607
5	YV1CZ5957A1559746
6	YV1CZ5957A1561287
7	YV1CZ5957A1562826
8	YV1CZ5957A1563640
9	YV1CZ5957A1565735
10	YV1CZ5957A1566820