

Recall Detail	
Ref No.	10000411
Manufacturer	Land Rover
Vehicle Class	N1 – Light Goods Vehicle
Model/Type	Defender
Dealer (phone no. / e-mail)	British Motors Limited - (Tel: 2821 7100 or 2820 5150 / service@britishmotors.com.hk)
Subject	Replacement of front seat belt brackets
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Front seat belt mounting brackets might detach as a result of the securing bolts being fractured due to being overly brittle.
Remedial Action	To replace the seat belt brackets
Build Dates	2011 to 2012
Launch Date	19 June 2012
Tentative Date of Recall Completion	31 December 2016

1 SALLDVBS7BA409185