

Recall Detail

Ref No	10000427
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	SC430
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Front Passenger Air Bag Inflators
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to the front passenger air bag inflators which could have been assembled with improperly manufactured propellant wafers. Improperly manufactured propellant wafers could cause the inflator to rupture and the front passenger air bag to deploy abnormally in a crash, which could result in increase of the risk of injury to the occupant.
Remedial Action	Inspect or replace the front passenger air bag inflator
Build Dates	November 2000 – March 2004
Launch Date	11 April 2013
Tentative Date of Recall Completion	December 2018

1	JTHFN48Y000011107
2	JTHFN48Y100027364
3	JTHFN48Y200007429
4	JTHFN48Y200013490
5	JTHFN48Y300013577
6	JTHFN48Y300015927
7	JTHFN48Y300030847
8	JTHFN48Y400013717
9	JTHFN48Y500013032
10	JTHFN48Y500013354
11	JTHFN48Y500015704
12	JTHFN48Y600011211
13	JTHFN48Y600013301
14	JTHFN48Y600014920
15	JTHFN48Y600017283
16	JTHFN48Y600032107
17	JTHFN48Y700008768
18	JTHFN48Y700013209
19	JTHFN48Y700013288

20	JTHFN48Y700013548
21	JTHFN48Y700016840
22	JTHFN48Y800013090
23	JTHFN48Y800015129
24	JTHFN48Y900013079
25	JTHFN48Y900013552
26	JTHFN48Y900017049
27	JTHFN48YX00012913
28	JTHFN48Y200026028
29	JTHFN48Y800034649