

Recall Detail	
Ref No	10000430
Manufacturer	Mitsubishi Motors Corporation
Vehicle Class	Light Goods Vehicle
Model/Type	L200 Sportero (KB4T)
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Diesel Injection System
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to excessive fuel injection caused by inadequate SQL (Small Quantity Learning) value of injector. Low engine power (performance), poor idling, MIL ON and engine stalling may be shown due to clogged DPF (Diesel Particulate Filter).
Remedial Action	Reprogram the engine-ECU, perform the SQL and implement DPF regeneration.
Build Dates	2012
Launch Date	20/05/2013
Tentative Date of Recall Completion	19/05/2014

1	MMCJYKB40CD014566	20	MMCJYKB40CD024384
2	MMCJYKB40CD014642	21	MMCJYKB40CD024378
3	MMCJYKB40CD014673	22	MMCJYKB40CD024389
4	MMCJYKB40CD014698	23	
5	MMCJYKB40CD016291	24	
6	MMCJYKB40CD016294	25	
7	MMCJYKB40CD016299	26	
8	MMCJYKB40CD016296	27	
9	MMCJYKB40CD016309	28	
10	MMCJYKB40CD016288	29	
11	MMCJYKB40CD021393	30	
12	MMCJYKB40CD021413	31	
13	MMCJYKB40CD021416	32	
14	MMCJYKB40CD021997	33	
15	MMCJYKB40CD023729	34	
16	MMCJYKB40CD023758	35	
17	MMCJYKB40CD024359	36	
18	MMCJYKB40CD024366	37	
19	MMCJYKB40CD024372	38	