

Recall Detail	
<b>Ref No</b>	<b>10000439</b>
<b>Manufacturer</b>	Mitsubishi Motors Corporation
<b>Vehicle Class</b>	Light Goods Vehicle
<b>Model/Type</b>	L200 SPORTERO (KB4T)
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	Front suspension lower arm inspection
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Owing to improper welding on the Lower Arm Assy., the Lower Arm Assy. may be broken leading to unstable steering and moving from one side to another.
<b>Remedial Action</b>	Inspection of Front suspension lower arm and replace it if necessary.
<b>Build Dates</b>	2011-2012
<b>Launch Date</b>	04/09/2013
<b>Tentative Date of Recall Completion</b>	03/09/2014

1	MMCJRKB40BD032833	21	
2	MMCJRKB40BD032915	22	
3	MMCJRKB40BD033055	23	
4	MMCJRKB40BD033213	24	
5	MMCJRKB40BD033358	25	
6	MMCJRKB40BD033473	26	
7	MMCJRKB40BD033708	27	
8	MMCJYKB40CD014566	28	
9	MMCJYKB40CD014642	29	
10	MMCJYKB40CD014673	30	
11	MMCJYKB40CD014698	31	
12	MMCJYKB40CD016291	32	
13	MMCJYKB40CD016294	33	
14	MMCJYKB40CD016299	34	
15	MMCJYKB40CD016296	35	
16	MMCJYKB40CD016309	36	
17	MMCJYKB40CD016288	37	
18		38	
19		39	
20		40	