

Recall Detail

Ref No	10000444
Manufacturer	AUDI
Vehicle Class	Private Car
Model/Type	A8
Dealer (phone no)	Premium Motors Ltd (3465 0000)
Subject	Replacing glass sliding roof panel
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	On Audi A8 vehicles with glass sliding/tilting sunroof (PR number 3FE) manufactured within a specific period, an unfavourable stress distribution was set up in the glass roof panel during production. This can cause the glass panel to break unexpectedly. This usually happens when a door is slammed closed while the vehicle is stationary. The panel consists of single-layer safety glass, which crumbles into small pieces in the event of breakage. A slight risk of injury caused by falling pieces of glass cannot be entirely ruled out.
Remedial Action	The production date of the glass sliding roof panel must be checked on the affected vehicles and the panel must be replaced if necessary.
Build Dates	Model Year: 2011 - 2014
Launch Date	30 Oct 2013
Tentative Date of Recall Completion	30 Oct 2014

1	WAUZZZ4H4DN028553
2	WAUZZZ4H6DN032104
3	WAUZZZ4H6DN032183
4	WAUZZZ4HXDN032588
5	WAUZZZ4H7DN032600
6	WAUZZZ4H3DN033842