

Recall Detail	
<b>Ref No</b>	<b>10000450</b>
<b>Manufacturer</b>	Mitsubishi Motors Corporation
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	ASX (GA3W) / LANCER (CY3A)
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	Engine idle speed not enough
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Due to improper programming of Engine ECU. Engine may stall due to lack of intake air or lean burn at idling.
<b>Remedial Action</b>	Reprogram the Engine ECU.
<b>Build Dates</b>	2011-2012
<b>Launch Date</b>	22/11/2013
<b>Tentative Date of Recall Completion</b>	21/11/2014

1	JMYSTCY3ABU000201
2	JMYSTCY3ABU000204
3	JMYSTCY3ABU000205
4	JMYSTCY3ABU000206
5	JMYSTCY3ABU000207
6	JMYSTCY3ABU000209
7	JMYSTCY3ABU000226
8	JMYSTCY3ABU000228
9	JMYXTGA3WBZ000102
10	JMYXTGA3WBZ000103
11	JMYXTGA3WBZ000104
12	JMYXTGA3WBZ000105
13	JMYXTGA3WBZ000106
14	JMYXTGA3WBZ000109
15	JMYXTGA3WBZ000110
16	JMYXTGA3WBZ000111
17	JMYXTGA3WBZ000115
18	JMYXTGA3WBZ000116
19	JMYXTGA3WBZ000117
20	JMYXTGA3WBZ000118

21	JMYXTGA3WBZ000119
22	JMYXTGA3WBZ000120
23	JMYXTGA3WBZ000121
24	JMYXTGA3WBZ000122
25	JMYXTGA3WBZ000123
26	JMYXTGA3WBZ000124
27	JMYXTGA3WBZ000125
28	JMYXTGA3WBZ000127
29	JMYXTGA3WBZ000130
30	JMYXTGA3WBZ000132
31	JMYXTGA3WBZ000134
32	JMYXTGA3WBZ000135
33	JMYXTGA3WBZ000139
34	JMYXTGA3WCZ000111
35	JMYXTGA3WCZ000112
36	JMYXTGA3WCZ000113
37	
38	
39	
40	