

Recall Detail

Ref No	10000457
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	X1, X3, 3 series and 5 series (E8x, F1x, F2x and F3x)
Dealer (phone no)	31936688
Subject	Check camshaft
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	Due to a possible camshaft manufacturing defect, the brake power assistance system may not be guaranteed.
Remedial Action	Check the depth measurement of the inlet camshaft sealing cover, retrofit the spring steel sleeve or, if necessary, replace the camshaft and vacuum pump.
Build Dates	03/2011-11/2013
Launch Date	14/12/2013
Tentative Date of Recall Completion	30/06/2014

1	A269130
2	D121699
3	D121760
4	D121767
5	D121856
6	D121857
7	D121865
8	D121866
9	D121922
10	D121923
11	D122234
12	D122291
13	D291416
14	D291419
15	D291463
16	D291467
17	D291474
18	D291476
19	D291500
20	D291534

21	D291544
22	D291568
23	D291569
24	D291571
25	D291572
26	D291580
27	D291581
28	D291582
29	D291583
30	D291601
31	D291609
32	D291612
33	D291620
34	D291654
35	D291656
36	D291671
37	D291684
38	D291699
39	D291717
40	D291718