

## Recall Detail

<b>Ref No</b>	<b>10000460</b>
<b>Manufacturer</b>	Toyota
<b>Vehicle Class</b>	LGV
<b>Model/Type</b>	Hiace Petrol Van
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4988)
<b>Subject</b>	Replacement of valve springs
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The corrosive pitting on the surface of valve springs could lead to fatigue cracks, which could result in breakage of the valve spring over time. In some cases, the engine could fail and stop while the vehicle is being driven, increasing the risk of a crash.
<b>Remedial Action</b>	Replace valve springs
<b>Build Dates</b>	June 2013 - July 2013
<b>Launch Date</b>	7 November 2013
<b>Tentative Date of Recall Completion</b>	December 2017

1
---

JTFHX02P400080225
-------------------