

Recall Detail

Ref No	10000464
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Wish
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Shift control cable nut inspection
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	It is due to improper tighten of the shift control cable nut during vehicle assembly, the nut could loosen, causing impossible and/or not smoothly shift change. If the vehicle is continuously operated in this condition, the nut could eventually come off, and the shift cable could separate from the neutral start switch lever, causing a loss of transmission shift ability and increasing the risk of a crash.
Remedial Action	Inspect and, if necessary, tighten the shift control cable nut
Build Dates	December 2013
Launch Date	14 March 2014
Tentative Date of Recall Completion	December 2015

1	JTDGG20W60J000766
---	-------------------