

Recall Detail	
Ref No	10000468
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	X5, 3 series and 4 series (F15 and F3x)
Dealer (phone no)	31936688
Subject	Check the rear-axle differential and replace if necessary
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	As part of on-going quality analysis at BMW, it has been established that the differential bevel gears in the rear-axle differential may not have been hardened. Non-hardened differential bevel gears may wear. This can cause the rear-axle differential to emit loud noises. If the defective rear-axle differential is not replaced in good time, this may cause the vehicle to break down.
Remedial Action	Check the rear-axle differential and replace if necessary
Build Dates	07/2013-01/2014
Launch Date	19/02/2014
Tentative Date of Recall Completion	30/09/2014

1	0C49452
2	0C49453
3	0C49454
4	0C49455
5	0C49456
6	0C49458
7	0C49459
8	0C49472
9	0C49473
10	0C49474
11	0C49476
12	0C49480
13	0C49482
14	0C49483
15	0C49485
16	0C49489
17	0C49501
18	0C49504
19	0C49506

20	0C49508
21	0C49510
22	0C49515
23	0C49518
24	0C49519
25	0C49520
26	0C49521
27	0C49522
28	0C49523
29	0C49691
30	0C49693
31	0C49694
32	0C49697
33	0C49700
34	0C49701
35	0C49702
36	0C49703
37	F710165
38	F728621

39	F728622
40	F728623
41	F999556
42	J783201
43	J783205
44	J783208
45	J783209
46	J783210
47	J783211
48	J783212
49	NR06614
50	NR06615
51	NR06616
52	NR06617
53	NR06618
54	NR06620
55	NR06627
56	NR06628
57	NR06629
58	NR06631
59	NR06664
60	NR06665
61	NR06666
62	NR06667
63	NR06673
64	NR06674
65	NR06691
66	NR06693
67	NR06696
68	NR06708
69	NR06710
70	NR06711
71	NR06712
72	NR06717
73	NR06846
74	NS62209
75	NS62210