

Recall Detail

Ref No	10000478
Manufacturer	Volvo
Vehicle Class	Private Car
Model/Type	V40 T4 PLUS / V40 T4 R-DESIGN
Dealer (phone no)	29273399
Subject	CEM software upgrade
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Left rear positioning light may stop functioning and the bulb failure light display a message in the instrument panel
Remedial Action	Software upgrade
Build Dates	2013 & 2014
Launch Date	4 July 2014
Tentative Date of Recall Completion	31 December 2014

1	YV1MV485BE2124925
2	YV1MV485BE2125048
3	YV1MV485BE2125059
4	YV1MV485BE2125117
5	YV1MV485BE2125294
6	YV1MV485BE2125389
7	YV1MV485BE2125395
8	YV1MV485BE2125430
9	YV1MV485BE2125499
10	YV1MV485BE2126681
11	YV1MV485BE2128980
12	YV1MV485BE2129556
13	YV1MV485BE2130496
14	YV1MV485BE2130616
15	YV1MV485BE2130706
16	YV1MV485BE2130715
17	YV1MV485BE2131383
18	YV1MV485BE2132253
19	YV1MV485BE2132480
20	YV1MV485BE2132522

21	YV1MV485BE2132694
22	YV1MV485BE2132706
23	YV1MV485BE2132875
24	YV1MV485BE2133783
25	YV1MV485BE2133942
26	YV1MV485BE2134154
27	YV1MV485BE2134279
28	YV1MV485BE2134420
29	YV1MV485BE2134612
30	YV1MV485BE2134629
31	YV1MV485BE2134653
32	YV1MV485BE2134709
33	YV1MV485BE2134766
34	YV1MV485BE2134770