

Recall Detail	
Ref No	10000486
Manufacturer	Mitsubishi Motors Corporation
Vehicle Class	Private Car
Model/Type	ASX (GA3W)
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Brake booster failure
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to inappropriate installation of the switch sleeve in the brake booster, the switch sleeve may have a crack. As a result, a tip of the switch sleeve would break and the brake pedal would not be released resulting in the vehicle to be unable to restart.
Remedial Action	Inspection and replace Brake booster assy. if necessary.
Build Dates	2011
Launch Date	12/9/2014
Tentative Date of Recall Completion	11/9/2015

1	JMYXTGA3WBZ000102	21	
2	JMYXTGA3WBZ000103	22	
3	JMYXTGA3WBZ000104	23	
4	JMYXTGA3WBZ000105	24	
5	JMYXTGA3WBZ000106	25	
6	JMYXTGA3WBZ000109	26	
7	JMYXTGA3WBZ000110	27	
8	JMYXTGA3WBZ000111	28	
9	JMYXTGA3WBZ000115	29	
10	JMYXTGA3WBZ000116	30	
11	JMYXTGA3WBZ000117	31	
12	JMYXTGA3WBZ000118	32	
13	JMYXTGA3WBZ000119	33	
14	JMYXTGA3WBZ000120	34	
15	JMYXTGA3WBZ000121	35	
16	JMYXTGA3WBZ000122	36	
17	JMYXTGA3WBZ000123	37	
18	JMYXTGA3WBZ000124	38	
19	JMYXTGA3WBZ000125	39	
20		40	