

Recall Detail

Ref No	10000490
Manufacturer	AUDI
Vehicle Class	Private Car
Model/Type	Q7
Dealer (phone no)	Premium Motors Ltd (3465 0000)
Subject	Replacing vacuum line
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	On Audi vehicles with 3.0 ltr. TDI engine manufactured within a specific period, engine oil may, in isolated cases, enter the brake servo via the vacuum lines. This can cause damage to the diaphragm in the brake servo so that the degree of servo assistance for the brakes is reduced.
Remedial Action	The vacuum line must be replaced on the affected vehicles.
Build Dates	Model Year: 2012 - 2013
Launch Date	13 Oct 2014
Tentative Date of Recall Completion	13 Oct 2015

1	WAUZZZ4L2CD035266
2	WAUZZZ4L1CD035307
3	WAUZZZ4L0CD035699
4	WAUZZZ4L2CD035722
5	WAUZZZ4L4CD035818
6	WAUZZZ4L5CD035889
7	WAUZZZ4L4CD036399
8	WAUZZZ4L9CD036849
9	WAUZZZ4LXCD039436
10	WAUZZZ4L4CD040405
11	WAUZZZ4L1CD041138
12	WAUZZZ4L8CD041184
13	WAUZZZ4L0CD041194
14	WAUZZZ4LXCD041266
15	WAUZZZ4L0CD042247

16	WAUZZZ4L7CD042276
17	WAUZZZ4L7CD043329
18	WAUZZZ4L2CD043335